
02/17/2012 Oper onControlTicket vers. 1 JLD9 Original Page 1

***************** Order 41620567 PATR/INSP 60067 DIXON-VACA #2+ Order type T180 EL TRANS EXPENSE RECURRING Status PCNF DSEX NMAT PRC REL SETC User Status UNSC Start date 03/01/2012 End date 03/31/2012 FunctLocation 5 8 1 ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Equipment 40577182 000/005 SINGLE WOOD POLE MaintPlanGroup TLP **ECES** Main WrkCenter SACTO **ECES** Sacramento Priority E - Schd Compl Yr 0 MaintenancePlan MaintPlanItem Revision No. Partner VLC5 JO Address Conerly-Scott Veronica L. 12345 Phone 916/760-3344 Class ETLEQP Electric Transmission Line Equipment ETL FRAMINGCONFIG 002 TRI PIN ARM DEAD END LATITUDE 38.402685000000 LONGITUDE -121.911692000000 Class ETL POLE ETL-POLE 002 ETL FRAMINGCONFIG TRI PIN ARM DEAD END LATITUDE 38.402685000000 LONGITUDE -121.911692000000 Operation 0004 Transmission OH Detailed Inspection Work center ET TMAN1 ECES ELECTRIC TROUBLEMAN TRANSMISSION Control key INDT CompConf No. 16309575 Operation key ETL03 Milestone Work 12 MIN Activity type MO Duration 30 DAY Number 1 ?arlStartDate 03/01/2012 Start time 00:00:00 .ateEndDate 03/31/2012 End time 00:00:00



MIN

Total buffer

lctual work

180

MIN

Transmission Line Inspection Datasheet

inspector Name : __ Miles Inspected: <u> Cooper Date Inspection Completed : 3ープルーに</u> # Structures Inspected: 57

Plan Group Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Funct Loc Oper Volt ET Poles

: ETT.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE Line Miles : 16 M

Work Center ABC

MAT

: BFZ

: ET_TMANI ELECTRIC TROUBLEMAN TRANSMISSION Detailed Ground Inspections Medium Impact ISO :

Struct Order: 571

DIXON-VACA #2 9/192 RPL CONNECTORS (Maintain Steel Structures)

02/09/2012 02/10/2012

Inspection Findings Data

Line Last Inspected: 41630193

: 60 KV

18/387 Swon Man 1 100 Bout Wine	TRIPIN - KEFR	DWO MOZIYAN BROKEN BOND WINE	1 JUNO 19407 2400 BAN DOLE- RE	AGO CHOS BYWA (1) AUTO SPLICE INT	THAY CHOS 14-92	なまれ	CHO8 1 48AR)	THOU CHOS I YEAR THE PIN - REPEARE TO T	- 13/28 SWO4 CHOT 2 YUK KTN X ARN	CONNEC	/166 Swal CHIO 6 MONS DAMAGED POLE STUL	4/112 I HOW MC10 1 YUTE OVERSTRESSED POST	JOHNO! MC23 2MON DAMAGES POLE (6	4/5/ 5wo4	HOME GALLOLO	CONC ZOOM OIL	THE MOST OFFICE	0/8 740	0-1	# Frictity Comments
						+	- -				-		1		•		-		H K	i Mi
																	-		Yes/No/Hot	Clearance
						+														

Supervisor's Initials:

1-1-1-1

Transmission Line Inspection Datasheet

Inspector Name: COPEN Date Inspection Completed: 3-29-12

Miles Inspected: # Structures Inspected: 57 (

Oper Volt Plan Group Order Funct Loc : 41620567 : 60 KV ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE PATR/INSP 60067 DIXON-VACA #2+ Line Miles : 16 M MAT

Work Center : ET_TMAN1 BFZ

ELECTRIC TROUBLEMAN TRANSMISSION Detailed Ground Inspections Medium Impact

Struct Order: 571

DIXON-VACA #2 9/192 RPL CONNECTORS (Maintain Steel Structures)

02/09/2012 02/10/2012

Inspection Findings Data

Line Last Inspected: 41630193

2-14-12		3-23-12	3-19-12	3-5-12	Date Found
0/5	410/225 CF14 CHIO	A7/175	A5/100 1403 Mas	19/410 SWOG CHOT	Structure #
Iths Elos	CFLA	MAIO	IH03	Swoa	Object
Elos		,	Maz	CH07	Damage
2 4845	2,100	lyma	14847	1 year	Priority Comments
FASHED D.E. INSULATIVE	(2) Auto Splices IN CONDUCTOR AT POLE	XING MARKER MISSING	Į.	RTN X ARM BRACE MINOR Arm Rat	Comments
					Hrs
			~		Clearance Yes/No/Hot
185000901	106000346	לובסרטילון	744C000901	101_000za8	Notification #

Supervisor's Initials:

Date Reviewed: 4911

Supervisor's Initials: 3-8-12 3-5-12 Line Last Inspected: 41630193 Oper Volt Inspection Findings Data Funct Loc Plan Group Order Date Found | Structure | Object | Damage | Priority / Comments 3-23-12 A7/157 3-26-12 Transmission Line Inspection Datasheet 3-6-12 ψ -15-12 A10/216 19/402 18/386 14/309 208/4 7/376 18/389 16/350 75 ETI.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE 41620567 1237 ってい S Line Miles : 16 M ET Poles PATR/INSP 60067 DIXON-VACA #2+ DIXON-VACA #2 9/192 RPL CONNECTORS (Maintain Steel Structures) 10Mpletob CISANEDUP POLS INSTAILED RE-Arraches Fiberobric & BIE Claved up Pole/INSUL INSTAILED GON MARKER Dus out KIMMED du Miles Inspected: Inspector Name : LOOPEN Date Inspection Completed : 3-28-12 Buries Dunies Minor Work ABC MAT # Struct Order: 571 Work Center Insul Strips ANChon Anchon SINKIN DEB RES BFZ ET_TMAN1 Date Reviewed: ELECTRIC TROUBLEMAN TRANSMISSION Medium Impact Detailed Ground Inspections # Structures Inspected : 57\ Clearance Yes/No/Hot 02/09/2012 02/10/2012 ISO : Notification

Medium Impact

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections Date Inspected: 2-14-12Structures Inspected: From 0/1To 1/44Date Inspected: 3-15-12
Structures Inspected: From 1/45 To 3/78 Date Inspected: 3-21-12 Date Inspected: 3-21-12Structures Inspected: From 3/79To 4/112Date Inspected: 3-28-12 Structures Inspected: From 4/113 To 5/130 Date Inspected: 3-20-12
Structures Inspected: From 5/131 To 6/146 Date Inspected: 3-26-12 Structures Inspected: From 6/147 To 9/141 Date Inspected: 3-20-12
Structures Inspected: From 9/192 To 10/222 Date Inspected: 3-9-12 Structures Inspected: From 10/223 To 11/234 Date Inspected: 3-5-12 Structures Inspected: From 11/235 To 12/274Date Inspected: 3-6-12 Structures Inspected: From 12/275 To 13/240Date Inspected: 3-8-12Structures Inspected: From 13/291 To 17/362Notes:

Funct Loc: ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Date Inspected: From A5/120 To A7/151 Date Inspected: 3-25-12 Structures Inspected: From A7/152 To A9/199 Date Inspected: 2-24-12 Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A10/216 Date Inspected: From A10/216 Date Inspected: To B7/174 Date Inspected: From To Date Inspected: To To		Inspected by: Cooper
Date Inspected: From 17/363 To 18/378 Date Inspected: 3-5-12 Structures Inspected: From 18/379 To 19/410 Date Inspected: 3-4-12 Structures Inspected: From 14/411 To A3/79 Date Inspected: 3-19-12 Structures Inspected: From A3/080 To A5/119 Date Inspected: 3-28-12 Structures Inspected: From A5/120 To A7/151 Date Inspected: 3-23-12 Structures Inspected: From A7/152 To A9/199 Date Inspected: 2-24-12 Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A10/216 Date Inspected: 3-23-12 Structures Inspected: From A10/216 Date Inspected: Trom A10/216 Date Inspected: Trom To Date Inspected: From To	Funct Loc: ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-W Order: 41620567 PATR/INSP 60067 DIXON-VACA	#2+ Medium Impact #2+ Detailed Ground Inspections
Structures Inspected: 3-5-12 Structures Inspected: From 18/379 Date Inspected: 3-4-12 Structures Inspected: From 19/411 Date Inspected: 3-19-12 Structures Inspected: From A3/000 Date Inspected: From A5/120 Date Inspected: From A5/120 Date Inspected: From A5/120 Date Inspected: 3-23-12 Structures Inspected: From A7/152 Date Inspected: 2-24-12 Structures Inspected: From A9/200 Date Inspected: 3-23-12 Structures Inspected: From A10/215 Date Inspected: 3-23-12 Structures Inspected: From A10/216 Date Inspected: Trom To	Date Inspected: 3-6-12	
Date Inspected: 3-4-12 Structures Inspected: From 19/411 To A3/79 Date Inspected: 3-19-12 Structures Inspected: From A3/000 To A5/119 Date Inspected: 3-28-12 Structures Inspected: From A5/120 To A7/151 Date Inspected: 3-23-12 Structures Inspected: From A7/152 To A9/199 Date Inspected: 2-24-12 Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A9/200 To B7/174 Date Inspected: 5-23-12 Structures Inspected: From A10/216 Date Inspected: Trom A10/216 Date Inspected: Trom To	Structures Inspected: From 17/363	To 18/378
Date Inspected: 3-4-12 Structures Inspected: From 19/411 To A3/79 Date Inspected: 3-19-12 Structures Inspected: From A3/000 To A5/119 Date Inspected: 3-28-12 Structures Inspected: From A5/120 To A7/151 Date Inspected: 3-23-12 Structures Inspected: From A7/152 To A9/199 Date Inspected: 2-24-12 Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A9/200 To B7/174 Date Inspected: 5-23-12 Structures Inspected: From A10/216 Date Inspected: Trom A10/216 Date Inspected: Trom To	Date Inspected: 3-5-12	
Date Inspected: From A3/080 To A5/119 Date Inspected: S-18-12 Structures Inspected: From A5/120 To A7/151 Date Inspected: 3-23-12 Structures Inspected: From A7/152 To A9/199 Date Inspected: 2-24-12 Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A9/200 To B7/179 Date Inspected: To B7/179 Date Inspected: Trom A10/216 Date Inspected: From A10/216 Date Inspected: From A10/216 Date Inspected: From A10/216 Date Inspected: From To	Structures Inspected: From 18/379	To 19/410
Date Inspected: From A3/080 To A5/119 Date Inspected: S-18-12 Structures Inspected: From A5/120 To A7/151 Date Inspected: 3-23-12 Structures Inspected: From A7/152 To A9/199 Date Inspected: 2-24-12 Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A9/200 To B7/179 Date Inspected: To B7/179 Date Inspected: Trom A10/216 Date Inspected: From A10/216 Date Inspected: From A10/216 Date Inspected: From A10/216 Date Inspected: From To	Date Inspected: 3-4-12	,
Structures Inspected: From A3/080 To A5/114 Date Inspected: 3-28-12 Structures Inspected: From A5/120 To A7/151 Date Inspected: 3-23-12 Structures Inspected: From A9/100 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A10/216 Date Inspected: From A10/216 Structures Inspected: From To Date Inspected: Trom To Date Inspected: Trom To Date Inspected: Trom To Date Inspected: Trom To Date Inspected: From To	Structures Inspected: From 19/411	To A3/79
Structures Inspected: From A3/080 To A5/114 Date Inspected: 3-28-12 Structures Inspected: From A5/120 To A7/151 Date Inspected: 3-23-12 Structures Inspected: From A9/100 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A10/216 Date Inspected: From A10/216 Structures Inspected: From To Date Inspected: Trom To Date Inspected: Trom To Date Inspected: Trom To Date Inspected: Trom To Date Inspected: From To	Date Inspected: 3-19-12	
Date Inspected: From A5/120 To A7/151 Date Inspected: 3-25-12 Structures Inspected: From A7/152 To A9/199 Date Inspected: 2-24-12 Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A10/216 Date Inspected: From A10/216 Date Inspected: To B7/174 Date Inspected: From To Date Inspected: To To	Structures Inspected: From A3/080	To A5/119
Date Inspected: 3-23-12 Structures Inspected: From A7/152 To A9/199 Date Inspected: 2-24-12 Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A10/216 To B7/174 Date Inspected: Structures Inspected: From To Date Inspected:	Date Inspected: 3-28-12	
Date Inspected: 2-24-12 Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A10/216 To B7/17a Date Inspected: Structures Inspected: From To Date Inspected: From T	Structures Inspected: From A5/120	To A7/151
Date Inspected: 2-24-12 Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A10/216 To B7/17a Date Inspected: Structures Inspected: From To Date Inspected: From To	Date Inspected: 3-23-12	
Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A10/216 Date Inspected: To B7/174 Date Inspected: To	Structures Inspected: From A7/152	To A9/199
Structures Inspected: From A9/200 To A10/215 Date Inspected: 3-23-12 Structures Inspected: From A10/216 Date Inspected: To B7/17a Date Inspected: To	Date Inspected: 2-24-12	
Date Inspected: Structures Inspected: From To Pate Inspected: Structures Inspected: To ate Inspected: tructures Inspected: To otes:	Structures Inspected: From A9/200	To A10/215
Date Inspected: Structures Inspected: From To Pate Inspected: Structures Inspected: To ate Inspected: tructures Inspected: To otes:	Date Inspected: 3-23-12	,
Date Inspected: Structures Inspected: From To Pate Inspected: Structures Inspected: To ate Inspected: tructures Inspected: To otes:	Structures Inspected: From Alo/216	To B7/17a
Structures Inspected: From		
ate Inspected: From	Structures Inspected: From	_ To
ate Inspected: From	Date Inspected:	
tructures Inspected: From To otes:	tructures Inspected: From	То
tructures Inspected: From To otes:		
otes:	tructures Inspected: From	То
	otes:	<u>. </u>

Inspector Name: COOPER

Date Inspected: 2-14-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		Troduction Type, omica sabout
Access:		
HOST Tech ID/Equip #:	Notes	<u>. </u>
Lat:		
Long:		
000/001 SINGLE WOOD POLE		Total # of Attachments:
40589508	[]completed/new finding(s)	
TRI PIN ARM DEAD END	ore-existing cond chked	
MEDIUM EOP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: C015951	
38.401192000000	ENTER AT S.E. CORNE	ER OF VACA DIXON SUB PARKING LOT.
-121.9180730000		
000/002 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40669889	[]completed/new finding(s)	
FLAT PIN ARM	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: C015950	
38.401717000000	ENTER AT S.E. CORNE	R OF PARKING LOT AT VACA DIXON SUB.
-121.9174570000		
000/005 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40577182	Sompleted/new finding(s)	
TRI PIN ARM DEAD END	pre-existing cond chked	GUYSTUB LEANING, OUT OF LIDE
	[]not inspetd this patrol	
	Notes: '02 Survey: C015945	
38.402685000000		
-121.9116920000		
000/006 SINGLE WOOD POLE	sompleted/no problems	Total # of Attachments:
40767461	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015944	
38.402706000000		
-121.9109430000	13-1	
000/007 SINGLE WOOD POLE	descripted/no problems	Total # of Attachments:
40814251		
TRI PIN ARM	[] pre-existing cond chked	N An I Bosses Des
	[]not inspctd this patrol Notes: '02 Survey: C015943	* Arem! BRICES RAN
38.402698000000	MONITOR XARM	
-121.9102010000	PAINTIOR AARM	
-121.9102010000 000/008 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40823432	completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	1-005-1-0
aria A dat Chin's	[]not inspetd this patrol	LOOSE TIE WIRE - BROKE
	Notes: '02 Survey: C015942	
38.402675000000	and barvey. Colosia	
-121.9094590000		
000/009 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40865907	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: 102 Current CO1ED41	
38.402683000000	1 N-	WINTHUSE X AVM
-121.9087320000	Nut	O A A / 1.
000/010 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
10874353	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015940	
38.402694000000		
-121.9079880000		

Page 2

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Inspector Name : __

Date Inspected : _

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	110000	
Long:		
000/011 SINGLE WOOD POLE	[] [] [] [] [] [] [] [] [] [] [] [] [] [Total # of Attachments:
40612558	[]completed/no problems.	
	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015939	0
38.402705000000		
-121.9073330000		
000/012 SINGLE WOOD FOLE	completed/no problems	Total # of Attachments: 1
40599351	[] completed/new finding(s)	DIST-0310456 1
TRI PIN ARM DEAD END	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C015938	
38.402544000000		
-121.9068820000		
000/013 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40669893	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C015937	<u></u>
38.402276000000		
-121.9060150000		
000/014 SINGLE WOOD POLE		Total # of Attachments:
10665457	[] completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
144 2001	[] not inspetd this patrol	
	Notes: '02 Survey: C015936	
38.40222700000	Notes: '02 Survey: C015936	
-121.9052540000		
000/015 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40756174	[completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015935	
88.40224000000		
121.9046250000		V. Company of the com
000/016 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0767463	completed/new finding(s)	
RI POST	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015934	
8.402273000000		
121.9039150000		
00/017 SINGLE WOOD POLE		Total # of Attachments:
0825135	[]completed/new finding(s)	
NGLE 0-30 DEGREES	pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C015933	
8.402268000000		
121.9032460000		
00/018 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
0599377	[]completed/new finding(s)	DIST-0310456 1
RI PIN ARM DEAD END	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015932	
8.402510000000 121.9021540000		

Inspector Name: COPER

Date Inspected: 2-14-12

Funct Loc: ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		TIPO/OMIGE HIS GOO
Access:		
HOST Tech ID/Equip #:	Notes	The sales of the s
Lat:	Moces	
Long:		
000/019 SINGLE WOOD POLE	(completed/no problems	Total # of Attachments:
40695347		
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015931	
38.402654000000	()	Pole has "c" Truss
-121.9 01712 0000		I OUR WAS COLVOLS
000/020 SINGLE WOOD POLE	// rempleted/no problems	Total # of Attachments:
10654066	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015930	
8.402670000000		
121.9009680000		
000/021 SINGLE WOOD POLE	I learned at a 2/man and 1 man	Motor I # of New America
	[]completed/no problems	Total # of Attachments:
10756176		A PKOKE HE MIKE
TRI PIN ARM	pre-existing cond chked	
	[]not inspetd this patrol,	
	Notes: '02 Survey: C015929	
8.402691000000		
121.9002490000		
00/022 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0767465	() completed/new finding(s)	
RI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015928	
8.402673000000	,	
121.8994900000		
00/023 SINGLE WOOD POLE	Completed/no problems	Impa-1 4 - 5 7
0814253	_	Total # of Attachments:
	[completed/new finding(s)	
HORIZONTAL POST DELTA	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015927	
8.402662000000		
121.8987650000		
00/024 SINGLE WOOD POLE]completed/no problems	Total # of Attachments:
0813427		
RI PIN ARM	[Apre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015926	
8.402638000000	1 301.0,1. 0013320	
121.8979860000		
00/025 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0875450	N -	
]completed/new finding(s)	
NGLE 0-30 DEGREES	[\pre-existing cond chked	
	[]hot inspetd this patrol	
	Notes: '02 Survey: C015925	
3.402655000000		
L21.8972790000		
01/026 SINGLE WOOD POLE	K]completed/no problems	Total # of Attachments:
0865367	[]completed/new finding(s)	
NGLE 0-30 DEGREES	[]pre-existing cond chked	
	_	
	I I I I I I I I I I I I I I I I I I I	
	[]not inspctd this patrol	
8.402341000000	Notes: '02 Survey: C015924	

Inspector Name: COOPER

Date Inspected: 2-14-12

Funct Loc : ETL.6740.POLE.WOOD

OD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Desc of Tech ID	ITaganation Boguit	Attachments #
	Inspection Result	
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:	37-6	
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	1	
001/027 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40612543	[] completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015923	
38.402348000000		
-121.8958580000		
001/028 SINGLE WOOD POLE	> completed/no problems	Total # of Attachments:
40599366	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015922	
38.402309000000	11.000 02 But Voy 1 0013322	
-121.895009000 -121.8950090000		
	N. Garanti at and Variation in the	Maral st of Attractivents.
001/029 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40669898	[completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
HEAVY EQP (CRANES, TRACTOR)	[]not inspetd this patrol	
	Notes: '02 Survey: C015921	
38.402383000000	ON WEBER EAST OF LE	WIS
-121.8942000000		
001/030 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40654068	[completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015920	
38.402364000000		
-121.8935630000		
001/031 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40756178	[] sompleted/new finding(s)	
TRI POST	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C015919	
38.40240000000	Notes: 402 Barvey: Colsys	
-121.8927870000	Margamal chad /na much lan-	Total # of Attachments:
001/032 SINGLE WOOD POLE	completed/no problems	
40767471	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015918	
38.402349000000		
-121.8919940000		
001/033 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40814255	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015917	<u> </u>
38.402354000000		
-121.8912560000		
001/034 SINGLE WOOD POLE		Total # of Attachments:
40823438	[]completed/new finding(s)	
40823438 TRI PIN ARM	[]pre-existing cond chked	
IRI FIN ARM	[]not inspetd this patrol	
	Notes: '02 Survey: C015916	
30 40233000000	Notes: 702 Survey: C015916	
38.402338000000		
-121.8904800000		

Page 5

Inspector Name : COOPER

Date Inspected : 2-14-12

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		12-,
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	د م	
001/035 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40875440	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C015915	
38.402356000000	Notes: '02 Survey: C015915	
-121.8897080000		
001/036 SINGLE WOOD POLE	\ <u>\</u>	
40874359	completed/no problems	Total # of Attachments:
-***	[]completed/new finding(s)	
TRIANGLE POST 70	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015914	
38.402343000000		
-121.8889600000		
001/037 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40596041	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015913	
38.402320000000	12 2 2 3 3 4 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5	
-121.8881800000		ł
001/038 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40599387	[] completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
38.402316000000	Notes: '02 Survey: C015912	
-121.8874510000		ļ
001/039 SINGLE WOOD POLE		
40669902	completed/no problems	Total # of Attachments:
	[]completed/new finding(s)	
TRI FIN ARM	[]pre-existing cond chked	ì
	[] not inspctd this patrol	
	Notes: '02 Survey: C015911	
38.402324000000		
121.8867190000	k	
001/040 SINGLE WOOD POLE		Total # of Attachments:
10599354	(completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015910	
8.402315000000		
121.8860170000		
01/041 SINGLE WOOD POLE	completed no problems	Total # of Attachments:
0695377	[completed/new finding(s)	TOTAL # OF ACCOUNTERIES:
RI PIN ARM	[]pre-existing cond chked	
	(]not inspetd this patrol	
	Notes: '02 Survey: C015909	
8.402331000000	Modes: 'UZ Survey: CU15909	
	P	
121.8853150000	4	
01/042 SINGLE WOOD POLE		Total # of Attachments:
0665461	[]completed/new finding(s)	
RI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: 6015908	11 11 /
8.402329000000		the "Truss
121.8846230000	1 40/5	+tac (. " (V (.))

Inspector Name : _ Date Inspected:

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

: 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #	2-14
Equip #		Attachment Type/Owner Listed	/~\
Framing Config			5
Access:			1)
HOST Tech ID/Equip #:	Notes		1/
Lat:			- 17
Long:			- 17
001/043 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:	
40756180	[]completed/new finding(s)		- 11
TRI PIN ARM	[]pre-existing cond chked] [
1	[]not inspctd this patrol		11
	Notes: '02 Survey: C015907		
38.402330000000			- 11
-121.8839390000			1 1
001/044 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:	$\neg \neg$
40756087	[]completed/new finding(s)		
TRI PIN ARM	[]pre-existing cond chked		1.1
	[]not inspctd this patrol		{ \
	Notes: '02 Survey: C015906		
38.402322000000			(4
-121.8832730000	l /		
001/045 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:	3-15
40825123	[]completed/new finding(s)		13-11
TRI PIN ARM	[]pre-existing cond chked		-
	[]not inspetd this patrol		
	Notes: '02 Survey: C015905		
38.402303000000			-
-121.8825830000	()		
001/046 SINGLE WOOD POLE	[*completed/no problems	Total # of Attachments:	
40813429	completed/new finding(s)		
TRI PIN ARM	[]pre-existing cond chked		1 1
	[]not inspctd this patrol		/
	Notes: 102 Survey: C015904		
38.402321000000			
-121.8819030000		•	
001/047 SINGLE WOOD POLE	Xlcompleted/no problems	Total # of Attachments:	
40875423	[]completed/new finding(s)		
TRI PIN ARM	[]pre-existing cond chked		
	[]not inspetd this patrol		
	Notes: '02 Survey: C015903		
38.402322000000			
-121.8812350000			
001/048 SINGLE WOOD POLE	[]campleted/no problems	Total # of Attachments:	
40865369	empleted/new finding(s)	10 1	1
TRI PIN ARM	[]pre-existing cond chked	RENXAM - 1 year.	1
	[]not inspetd this patrol	CCN / MYN	
	Notes: '02 Survey: C015902		
38.402305000000			1 1
-121.8805600000			
001/049 SINGLE WOOD POLE	/completed/no problems	Total # of Attachments:	
40612546	[]completed/new finding(s)		
TRI PIN ARM	[]pre-existing cond chked		
	[]not inspetd this patrol		
	Notes: '02 Survey: C015901		
38.402326000000			
-121.8793860000	S		
001/050 SINGLE WOOD POLE	/ completed/no problems	Total # of Attachments: 1	
40589509	_	DIST-0310456 1	
TRI PIN ARM	[]pre-existing cond chked		
	[] not inspetd this patrol		
29 40222500000	Notes: '02 Survey: C015906	Pola Has C Trass	
38,402326000000		tale Has (1 lass)	I N
-121.8787650000		100 1103	

Inspector Name : COOPEN

Date Inspected : 3-15-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		·
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	-	
001/051 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40669906	[]completed/new finding(s)	
DOUBLE VERTICAL	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015899	
38.402306000000		
-121.8780470000		Dus ove Anchors
001/052 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40665464	[]completed/new finding(s)	,
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015898	
38.401674000000	•	
-121.8780630000		
002/053 SINGLE WOOD POLE	campleted/no problems	Total # of Attachments:
40756182	[]completed/new finding(s)	
TRI PIN ARM DEAD END	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015897	
38.401170000000		
-121.8780530000		
002/054 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40767473	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015896	
38.400535000000		
-121.8780380000		
002/055 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40825121	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015895	
38.399955000000	_	
-121.8780060000		
002/056 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40823456	[]completed/new finding(s)	
TRI PIN ARM	pre-existing cond chked	
	[]not inspetd this patrol	XArm Han - 14n
	Notes: '02 Survey: C015894	
38.39934900000		
-121.8780250000		
002/057 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40865909	sompleted/new finding(s)	
TRI PIN ARM]pre-existing cond chked	VAA- V
	[]not inspctd this patrol	XAM Ren & Ruch
	Notes: '02 Survey: C015893	(-12)
38.398776000000		
-121.8780310000		
002/058 SINGLE WOOD POLE	Acompleted/no problems	Total # of Attachments:
40874357	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015892	
38.398172000000		
-121.8779750000		

Inspector Name : COOPER Date Inspected: <u>3ー15ーに</u>

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	l Attachmant - I
Equip #	Pooling Kesult	Attachments #
Framing Config		Attachment Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	<u> </u>
Lat:	110000	
Long:	,	
002/059 SINGLE WOOD POLE		
40596044	completed/no problems	Total # of Attachments:
TRI PIN ARM	[]completed/new finding(s)	·
INI PIN ARM	[]pre-existing cond chked	
1	[]not inspetd this patrol	
28. 20555000000	Notes: '02 Survey: C015891	
38,397558000000	,	
-121.8779520000		
002/060 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40599388	[]completed/new finding(s)	in —— - Ta an Aminasa da j
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015890	
38.396947000000		
-121.8779490000		
002/061 SINGLE WOOD POLE	Acompleted/no problems	Total # of aller
40681685	[]completed/new finding(s)	Total # of Attachments:
TRI PIN ARM	[]pre-existing cond chked	
	I lear ingrees the	
	[]not inspetd this patrol	
38.396360000000	Notes: 102 Survey: C015889	
-121.8779910000	1	Has "c" Trus
002/062 SINGLE WOOD POLE	Jali.	HAS CIVEN
40665460	completed/no problems	Total # of Attachments:
TRI PIN ARM	[]completed/new finding(s)	
Marin T. Tra Maria	[]pre-existing cond chked	
	[]not inspetd this patrol	
39 395740000	Notes: '02 Survey: C015888	
38.395740000000		
-121.8780070000	L×	
002/063 SINGLE WOOD POLE 40756184	Completed/nc problems	Total # of Attachments:
	[] completed/new finding(s)	
TRI PIN	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015887	
38.394938000000		
-121.8 7 7969000 0		
002/064 SINGLE WOOD POLE	[]completed/no problems []	Total # of Attachments:
40767469	[]completed/new finding(s)	Wilder Wor. Attachments:
TRÏ PIN ARM	pre-existing cond chked	
	[]not inspetd this patrol	STUB POLE CANCEL > NOT NEEDED
	Notes: '02 Survey: C015886	- Ma TOTE CAPULEY / NOT NEDW
38.394490000000	22 2017el: C01288P	·
121.8779270000		
002/065 SINGLE WOOD POLE	completed/no problems T	
0814259	Completed/no problems T	otal # of Attachments;
RI PIN ARM	[] completed/new finding(a)	
	[]pre-existing cond chked	
	[]not inspetd this patrol	
8.393902000000	Notes: '02 Survey: C015885	
	,	İ
121.8779050000		
02/066 SINGLE WOOD POLE	/ completed/no problems T	otal # of Attachments:
0823436	[]completed/new finding(s)	
	[]pre-existing cond chked	
RI PIN ARM	r lbre-extreging cond cuked I	
RI PIN ARM	[] not inspetd this patrol	
RI PIN ARM	[]not inspetd this patrol	
	[] Inot inspetd this patrol Notes: '02 Survey: C015884	

Inspector Name : ______ Date Inspected : _

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567

-121.8778160000

Medium Impact

PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections Desc of Tech ID Inspection Result Attachments # Equip # Attachment Type/Owner Listed Framing Config Access: HOST Tech ID/Equip #: Notes Lat: completed/no problems 002/067 SINGLE WOOD POLE Total # of Attachments: 40589511 []completed/new finding(s) TRY PIN ARM []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015883 38,392698000000 -121.8779520000 Completed/no problems 002/068 SINGLE WOOD POLE Total # of Attachments: 40695352 [\completed/new finding(s) TRI PIN ARM []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015882 38.392109000000 -121.8779200000 002/069 SINGLE WOOD POLE]completed/no problems Total # of Attachments: 40659336 \completed/new finding(s) TRI PIN ARM []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015881 38.391478000000 -121.8778670000 002/070 SINGLE WOOD POLE]completed/no problems Total # of Attachments: 40756186 [\completed/new finding(s) TRI PIN ARM []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015880 38.390980000000 -121.8779100000 002/071 SINGLE WOOD POLE Completed/no problems Total # of Attachments: 40767467 completed/new finding(s) TRI PIN ARM []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015879 38.390290000000 -121,8778930000 002/072 SINGLE WOOD POLE [/]completed/no problems Total # of Attachments: 40814257 completed/new finding(s) TRI PIN ARM []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015878 38.389789000000 -121.8779050000 002/073 SINGLE WOOD POLE]completed/no problems Total # or Attachments: completed/new finding(s) 40823434 TRI PIN []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015877 38.389064000000 -121.8778630000 002/074 SINGLE WOOD POLE /]completed/no problems Total # of Attachments: []completed/new finding(s) 40865911 TRI PIN ARM []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015876 38.388473000000

Inspector Name : COOPER Date Inspected: 多つ니ーに

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

: 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result Attachments #
Equip #	
Framing Config	Attachment Type/Owner Listed
Access:	
HOST Tech ID/Equip #:	Notes
Lat:	
Long:	
002/075 SINGLE WOOD POLE	completed/no problems Total # of Attachments:
40874355	[]completed/new finding(s)
TRIANGLE POST 70	[]pre-existing cond chked
	I Inot inspetd this patrol Deg out DURISD Anchor Rob
	Notes: '02 Survey: C015875
38,387834000000	Notes: -02 survey: C015875
-121.8778410000	
002/076 SINGLE WOOD POLE	I Completed/no problems Total # of Attachments:
40596047	[]completed/new finding(s)
FRIANGLE POST 70	I pre-existing cond chked
	[]not inspetd this patrol
	Notes: '02 Survey: C015874
38.387157000000	
-121.8777190000	
002/077 SINGLE WOOD POLE SW 69	[]completed/no problems Total # of Attachments:
40599352	
	[]completed/new finding(s)
FIELD SWITCH STRUCTURE	Opre-existing cond chked
MEDIUM EQP(AERIAL LIFT; LINE TR	I not inspetd this patrol Clark Ven Around SW- Black Bunily
	Notes:
18.386742000000	
121.8777170000	
03/078 SINGLE WOOD POLE	Completed/no problems Total # of Attachments:
1122407	[] completed/new finding(s)
INE AND BUCK	[] Completed/new finding(s)
INE AND SUCK	[]pre-existing cond chked
	[]not inspetd this patrol
	Notes: '02 Survey: C015872 TO TRAVIS JCT Equip. not in GAD
8.385820000000	
121.8776470000	
03/079 SINGLE WOOD POLE SW 47	completed/no problems Total # of Attachments:
0665497	[] completed/new finding(s)
TELD SWITCH STRUCTURE	Completed/no problems Total # of Attachments: [] completed/new finding(s) [] pre-existing cond chked
VACA SCT	I look incord blic value
VITO ([]not inspctd this patrol
Д. 30 бориналова	Notes:
8.386027000000	1
121.8774870000	
03/080 SINGLE WOOD POLE	Completed/no problems Total # of Attachments:
0677815	()completed/new finding(s)
PIANGLE POST 70	[]pre-existing cond chked
	[] not inspetd this patrol
T-1(v/c)	Notes: '02 Survey: C015870
3.386587000000	Modes. 02 Sativey: Cutabili
	[· · · · · · · · · · · · · · · · · · ·
L21.8769770000	
03/081 SINGLE WOOD POLE	Completed/no problems Total # of Attachments:
05994 09	[\completed/new finding(s)
CIANGLE POST 70	[]pre-existing cond chked
TH(c)	[]not inspetd this patrol
1 41(~)	Notes: '02 Survey: C015869
.387256000000	
.21.8764050000	
121.8764050000 03/082 SINGLE WOOD POLE	Completed/no problems Total # of Attachments:
121.8764050000 03/082 SINGLE WOOD POLE 0612595	[]completed/new finding(s)
121.8764050000 03/082 SINGLE WOOD POLE 0612595 RIANGLE POST 70	[]completed/new finding(s) []pre-existing cond chked
8.387256000000 121.8764050000 03/082 SINGLE WOOD POLE 0612595 RIANGLE POST 70	[]completed/new finding(s) []pre-existing cond chked
121.8764050000 03/082 SINGLE WOOD POLE 0612595	[]completed/new finding(s) []pre-existing cond chked []not inspect this patrol
121.8764050000 03/082 SINGLE WOOD POLE 0612595 RIANGLE POST 70	[]completed/new finding(s) []pre-existing cond chked

Page 11

Inspector Name : _ Date Inspected :

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Order : 41620567	PATR/INSP 60067 DIX	ON-VACA #2+ Detailed Ground Inspectio
Desc of Tech ID	Inspection Persit	
Equip #	Inspection Result	Attachments #
		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	Notes	
_		
Long:		
003/083 SINGLE WOOD POLE	completed/no problems	
40868361	ombreced/110 broblems	Total # of Attachments:
TH(e)	[] completed/new finding(s)	1
- L/(c)	[]pre-existing cond chked	i i
((100)	[]not inspctd this patrol	
	Not on 100 F	
38.388418000000	Notes: '02 Survey: C015867	
•	700	RATTY CZOM POL
-121.8753650000	200	The court for
003/084 SINGLE WOOD POLE	completed/no problems	
40869028	1.completed/10 bropleme	Total # of Attachments:
	[] completed/new finding(s)	
TRI POST (H(C)	[]pre-existing cond chked	
1 (""		
	Notes: 100 5	
38.38898900000	Survey: C015866	Fully Drussip pate & Bas
	TOIL HAMMEL TES	TS OK: (73
-121.8748500000		OF Roch Jah
003/085 SINGLE WOOD POLE	[scmpleted/no problems	TS dK: Fully proses pole i Dag OF Roch labing ousite
40823476		Total # of Attachments:
TRI BOCT	[]completed/new finding(s)	
(e)	[]pre-existing cond chked	
TH(c)	[]not inspetd this patrol	
	Notone 100 for	
38.389573000000	Notes: '02 Survey: C015865	
-121.8743280000		
003/086 SINGLE WOOD POLE	completed/no problems	
40817776	1 1 - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Total # of Attachments:
	[]completed/new finding(s)	
THE POSS THEY	pre-existing cond chked	
(. (3	[]not inspetd this patrol	T
	Notes: '02 Survey: C015864	FOUND STUB TUSTAMED, WORK Completed
38.390189000000	Notes: 02 Survey: C015864	2011
-121.8737840000		
003/087 SINGLE WOOD POLE	completed/no problems	Total a C
41122284 THC)	[] completed/new finding(s)	Total # of Attachments:
HC)	tild inding(s)	
141 2031	pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015863	Pole Replace (Fours " Wass Inseally - ok
38.390793 000 000	. 02 3drvey: C015863	
121.8732710000		
003/088 SINGLE WOOD POLE	[]completed/no problems [7	Potral # ac and
10759684		Total # of Attachments: 1
TRI POST	completed/new finding(s)	DIST-0310456 1
2001	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015862	
8.391434000000	102 Survey: C015862	(0.1.1.
	1	DAMAS TO LY SAM
121.8727050000	1012	DAMASED BY AS EQUIP Replace
03/089 SINGLE WOOD POLE	Completed/no problems T	otal the court - 12 Explace
0759928	I complete discussion of	otal # of Attachments: 1
RI POST	[]completed/new finding(s) D	TST-0310456 1
	[]pre-existing cond chked	
1461	[]not inspctd this patrol	
	Notes: '02 Survey: C015861	
8.392079000000		
121.8721190000		
33/090 SINGLE WOOD POLE		
0657552		otal # of Attachments:
12	[]completed/new finding(s)	
HORIZONTAL POST DELTA SHORT	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Motor, 103 Comment	
392586000000	Notes: '02 Survey: C015860	
	Notes: '02 Survey: C015860	
3.392586000000 .21.8716510000	Notes: '02 Survey: C015860	

Inspector Name : _ Date Inspected : _

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

N F M TN		The state of the s
Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		1
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	Notes	
1		
Long:		
003/091 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40695473	[]completed/new finding(s)	ıl I
TRI TOST	[]pre-existing cond chked	
3HPDC)	[]not inspetd this patrol	1
	Notes: '02 Survey: C015859	'
38.393157000000		1
-121.8711520000		
003/092 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40592639	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
1 - (H(e)	[]not inspctd this patrol	
	Notes: '02 Survey: C015858	
38.393771000000	1 1/2)	·
-121.8705860000	KATTERO	LD CEDAR
003/093 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40868360	[]completed/new finding(s)	"
(4C)	[]pre-existing cond chked	
ノングノ	[]not inspetd this patrol	
	Notes: '02 Survey: C015857	
38.394368000000		
-121.8700810000		
003/094 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
	· · · -	
40875454	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
() (c)	[]not inspctd this patrol	
(HE)	Notes: '02 Survey: C015856	TECH ID=004/086
38.394979000000		22.00 22 000,000
-121.8695240000		
003/095 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40823474	[]completed/new finding(s)	1
TRI DOST	Spec-existing cond chked	
1 H(c)	[]not inspetd this patrol	REplace Insulation - No Changes
1	Notes: '02 Survey: C015855	HELONGE TOP MATOR 3 100 00 101
05 06550000000	Notes: 102 Barvey: Colsess	
38.39559000000		
-121.8690170000		
003/096 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40817774		
TRI POST	[]pre-existing cond chked	
	[]not inspetd this patrol	
146)	Notes: '02 Survey: C015854	
	-	1.10 11 1-
38.396103000000	MONITOR POSSIBLE N/	G POLE - LOOKS RATTO, HAMMEN TEST
-121.8685070000		/ OK
003/097 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40767504	[completed/new finding(s)	
MDT DOOM	[]pre-existing cond chked	
-(+(c)	[]not inspetd this patrol	
	_	
	Notes: '02 Survey: C015853	
38.396727000000		
-121.8680020000		
004/098 SINGLE WOOD POLE	(Completed/no problems	Total # of Attachments:
40768162	[]completed/new finding(s)	
20/00102		
ナーナーナー	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015852	
38.397317000000		
-121.8674250000		
-121.00/4230000		

Page 13

Inspector Name : COOPER Date Inspected : 3-21-12

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	•	Attachment Type/Owner Listed
Framing Config		17
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
004/099 SINGLE WOOD POLE	/lcompleted/no problems	m-t-2 # -C 244-24
		Total # of Attachments:
40665503	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
TH(C)	[]not inspetd this patrol	
•	Notes: '02 Survey: C015851	
38.397943000000		
-121.8669130000		
004/100 SINGLE WOOD POLE	//completed/no problems	Total # of Attachments:
40677810	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
TH(c)	[]not inspctd this patrol	
	Notes: '02 Survey: C015850	· · · · · · · · · · · · · · · · · · ·
38,398583000000		
-121.8663550000		
004/101 SINGLE WOOD POLE	Completed/no problems	Total # of Artachments.
1 '		Total # of Attachments:
40599390	(]completed/new finding(s)	
TRI FUST (C)	()pre-existing cond chked	
(' ' ' ' '	[]not inspctd this patrol	
	Notes: '02 Survey: C015849	
38.399144000000	1	
-121.8658420000		
004/102 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40612592	[]completed/new finding(s)	
40612592 FRI 2005# (1+(C)	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015848	
30 30050300000	Noces: .02 survey: C015848	
38.39969300000		
-121.8653440000		
004/103 SINGLE WOOD FOLE	eompleted/no problems	Total # of Attachments:
40874389	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
(2)	[]not inspctd this patrol	
`	Notes: '02 Survey: C015847	
38.400273000000		
-121.8648230000		
004/104 SINGLE WOOD POLE	[completed/no problems	Total # of Attachments:
40869026	[]completed/new finding(s)	
	[]pre-existing cond chked	
(°)		
TH(e)	[]not inspetd this patrol	
	Notes: '02 Survey: C015846	,
38.400898000000	A Die Mas "	Chance
-121.8642620000	1 4 4 W 4147	C 70 1455
004/105 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40823478	[]completed/new finding[s]	
TRI PIN ARM DEAD END	[]pre-existing cond chked	
	[] not inspctd this patrol	
	Notes: '02 Survey: C015845	
38.401483000000	\mathcal{D}_{i}	() C = 1
-121.8637430000	Tole HA>	Wood Stub
004/106 SINGLE WOOD POLE	Sompleted/no problems	Total # of Attachments:
40817772	1]completed/new finding(s)	
TRI POST	[)pre-existing cond chked	
ンエの)	[] not inspetd this patrol	
(a) H/	Notes: '02 Survey: C015844	
38 40232000000	Modes: 02 Survey: C015844	
38.402129000000		
-121.8631480000	I	

Inspector Name : _____ Date inspected : _

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Medium Impact

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Desc of Tech ID	Inspection Result	Attachments #
Equip #		
Framing Config		Attachment Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
04/107 SINGLE WOOD POLE		[man=1 # = 6 744 1
0759681 (-)(6)	[]completed/new finding(s)	Total # of Attachments:
INE AND BUCK to lack stank	[]pre-existing cond chked	
THE PACK NO CHOMA STORY	I lose issuing cond caked	
	[]not inspetd this patrol	
8.402641000000	Notes: '02 Survey: C015843	BATAVIA TAP
121.8626800000		
04/108 SINGLE WOOD POLE		Total # of Attachments:
0768142	[]completed/new finding(s)	
TOST (WC)	[]pre-existing cond chked	
(n/c)	[]not inspetd this patrol	
•	Notes: '02 Survey: C015842	I
3.403276000000	32 32 33 4 4023042	
.21.8621610000		
4/109 SINGLE WOOD POLE	(Sampleted/sec. 2	(m. c.) (c.)
0665525		Total # of Attachments:
	[]completed/new finding(s)	
W/C)	[]pre-existing cond chked	
	[]not inspetd this patrol	
•	Notes: '02 Survey: C015841	
.403797000000		
21.8616830000		
4/110 SINGLE WOOD POLE	() completed/no problems	Total # of Attachments:
677806	[]completed/new finding(s)	1 of Meaning 1001
1 POST	[]pre-existing cond chked	
T_/ (N/C)		
~~~~	[]not inspetd this patrol	
404266000000	Notes: '02 Survey: C015840	
.404366000000		i
21.8611870000		
4/111 SINGLE WOOD POLE	Sompleted/no problems	Total # of Attachments:
586218	[ ]completed/new finding(s)	
L DOST	[ ]pre-existing cond chked	
T=1 (N/C)	[ ]not inspetd this patrol	
ーハードはアン	Notes: '02 Survey: C015839	
.405050000000		1
21.860600000		
4/112 SINGLE WOOD POLE	]completed/no problems	Moheat III a Z
374385		Total # of Attachments:
	[ completed/new finding(s)	1100 - ( )
7-1 (HC)	[ ]pre-existing cond chked	N/C POST INSUL (TOP &) OVERSTRESSED
ハー・しつ)	[ ]not inspetd this patrol	, , ( Mb> ) - 0 000 ( 1000 ET)
	Notes: '02 Survey: C015838	
405541000000		
1.8601070000	Supplied NEW GAT	TE TO Propower to Instant For Acq55
/113 SINGLE WOOD POLE	completed/no problems	Total # of Atherbrooks, 1
75456	[]completed/new finding(s)	DISTRICT OF ACCOUNTERS: 1
POST		DIST-0310456 1
	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015837	
405886000000	REFRAME POLE 8/14/20	01 - COMPLETED NOTIFICATION ON 12/22/2003 - ENTERED
1.8596290000	INTO EQUIPMENT RECORD	E ON 12/22/2003
/114 SINGLE WOOD POLE		Total # of Attachments:
	[]completed/new finding(s)	
	[]pre-existing cond chked	
-		
-	[]not inspetd this patrol	
	Notes: '02 Survey: C015836	
406331000000		
1.8589510000		1

Page 15

Inspector Name : _ Coope Date Inspected: 3-28-12

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		]
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
004/115 SINGLE WOOD POLE	completed/no problems	
40817770	completed/no problems	Total # of Attachments:
ANGLE 30-80 DEGREES	[ ]completed/new finding(s)	
	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
38.406716000000	Notes: '02 Survey: C015835	
-121.8583370000		
004/116 SINGLE WOOD POLE 40767502	completed/no problems	Total # of Attachments:
<del></del>	[ completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspotd this patrol	
	Notes: '02 Survey: C015834	
38.407188000000		
-121.8581570000		
004/117 SINGLE WOOD POLE	Completed/no problems	
40768148	Completed/new finding(s)	Total # of Attachments:
TRI POST DEAD END 60	( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )	
	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
38.407855000000	Notes: '02 Survey: C015833	
-121.8579830000		
004/118 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40665522	[   Completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015832	
38.408251000000		
121.8577470000		
04/119 SINGLE WOOD POLE	completed/no problems	
0695452		Total # of Attachments:
RI POST	[ ]pre-existing cond chked	
	I Thre-existing cond chied	
	[]not inspetd this patrol	
8.408892000000	Notes: '02 Survey: C015831	
121.8572560000		
05/120 SINGLE WOOD POLE		
	completed/no problems	Potal # of Attachments:
0592638	lcompleted/new finding(s)	
RI POST	[\]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015830	
8.409442000000		
121.8567120000		
05/121 SINGLE WOOD POLE		
0590230	[] completed/new finding(s)	otal # of Attachments.
RI POST		
	[]pre-existing cond chked	
	[]not inspetd this patrol	
.410059000000	Notes: '02 Survey: C015829	
21.8562630000	U	
	completed/no problems T	otal # of Attachments:
874391	[ ]completed/new finding(s)	
I POST	[ ]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015828	
.410641000000	/	
21.8556390000		

Inspector Name : COOKY Date Inspected : _

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
005/123 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40875473	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
181 1001	[ ]not inspctd this patrol	
38.41210000000	Notes: '02 Survey: C015827	
-121.8550600000		<u> </u>
005/124 SINGLE WOOD POLE		Total # of Attachments:
40823480	[ ]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015826	
38.411822000000		
-121.8545630000		
005/125 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40817768	[]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015825	
38.412610000000	2 barvey. co13625	
-121.8539900000		
005/126 SINGLE WOOD POLE		The state of the s
005/126 SINGLE WOOD FOLE 40767506		Total # of Attachments:
40767506 TRI POST	[]completed/new finding(s)	
IRI POST	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015824	
38.413159000000		
-121.8534100000		
005/127 SINGLE WOOD POLE		Total # of Attachments:
40768146	[ ]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015823	
38.413878000000	-	
-121.8527930000	( )	
105/128 SINGLE WOOD POLE	Nompleted/no problems	Total # of Attachments:
10657550	[]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015822	
8.414616000000	Notes: 'UZ Survey: C015822	
121.8521090000	X	
05/129 SINGLE WOOD POLE		Total # of Attachments:
0677802	[ ]completed/new finding(s)	
RT POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015821	
0.415070000000		
8.4725/000000		
121.8515290000	Completed/no problems	Total # of Attachments:
121.8515290000 05/130 SINGLE WOOD POLE		Total # of Attachments:
121.8515290000 05/130 SINGLE WOOD POLE 0599391	[ ]completed/new finding(s)	Total # of Attachments:
121.8515290000 05/130 SINGLE WOOD POLE 0599391	[]completed/new finding(s) []pre-existing cond chked	Total # of Attachments:
88.41527000000 121.8515290000 005/130 SINGLE WOOD POLE 0599391 PRI POST	[]completed/new finding(s) []pre-existing cond chked []not inspctd this patrol	Total # of Attachments:
121.8515290000 05/130 SINGLE WOOD POLE 0599391	[]completed/new finding(s) []pre-existing cond chked	Total # of Attachments:

Page 17

Inspector Name : COOPE Date Inspected : 3

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID Equip #	Inspection Result	Attachments #
Framing Config		Attachment Type/Owner Listed
Access:		11 / 11 - 12 - 2000
HOST Tech ID/Equip #:	Notes	<u></u>
Lat:	;	•
Long:		
005/131 SINGLE WOOD POLE	recompleted/no problems	Total # of Attachments:
40665505	[ ]completed/new finding(s)	Total # Of Actachments:
TRI POST /	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015819	<u> </u>
38.416575000000		
-121.8503420000		
005/132 SINGLE WOOD POLE	Completed/no problems	
40677798	1 sompleted/no problems	Total # of Attachments:
TRI DOST ~ (C)	[ ]completed/new finding(s)	
THE POST (C)	[ ]pre-existing cond chked	
•	[ ]not inspctd this patrol	
38.416909000000	Notes: '02 Survey: C015818	
-121.8500420000		
005/133 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
10599393	[ ] completed/new finding(s)	
PRI POST 3HPP (C)	[ ]pre-existing cond chked	
CANA.	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015817	
8.417182000000		
121.8498040000		
05/134 SINGLE WOOD POLE		
0601256	[ ]completed/new finding(s)	Total # of Attachments:
NGLE 30-80_DEGREES	[ ]pre-existing cond chked	
100	lact inspetd by	
1////	[]not inspetd this patrol	
8.417941000000	Notes: '02 Survey: C015816	
121.8491410000		
05/135 SINGLE WOOD POLE		
0874393	completed/no problems	Total # of Attachments:
Test / (C)	<pre>1   Completed/new finding(s)</pre>	
	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
1100000000	Notes: '02 Survey: C015815	
3.41870000000		
21.8484890000		
05/136 SINGLE WOOD POLE	Completed/no problems   T	otal # of Attachments:
869024	[ ]completed/new finding(s)	- " Mendaliettes:
I POST	[ ]pre-existing cond chked	
161	[ ]not inspetd this patrol	
•	Notes: '02 Survey: C015814	
.419407000000		
21.8478170000		
	completed/no problems T	
823492	I loompleted/no problems T	otal # of Attachments:
I POST - (C)	[] dompleted/new finding(s)	
イーペー	[ ]pre-existing cond chked	
•	[]not inspetd this patrol	
. 420127000000	Notes: '02 Survey: C015813	
21.8471620000		
7		
5/138 SINGLE WOOD POLE	Teompleted/no problems To	tal # of Attachments:
317766	[ ]completed/new finding(s)	
- L - L - L - L - L - L - L - L - L - L		
I FOST	[ ]pre-existing cond chked [	
I FOST	[]pre-existing cond chked []not inspctd this patrol	
FOST (	[ ] not inspctd this patrol	
POST (	[] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015812	

Page 18

Inspector Name : Cooksil Date Inspected : 3

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inchestion Bosula	
Equip #	Inspection Result	Attachments #
Framing Config		Attachment Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	Notes	
Long:		
006/139 SINGLE WOOD POLE		
40759679		Total # of Attachments:
	[ )completed/new finding(s)	
TRI POST (-(C)	[ ]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
20 40174000000	Notes: '02 Survey: C015811	
38.421342000000		
-121.8461250000		T
006/140 SINGLE WOOD POLE 40759926	sompleted/no problems	Total # of Attachments:
	[]completed/new finding(s)	
TRE POST ( )	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
BB 4535555555	Notes: '02 Survey: C015810	
38.421898000000		
-121.8456040000		
006/141 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40665520	[ ]completed/new finding(s)	
17 (C)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015809	
38.422499000000		i
-121.8450730000		
006/142 SINGLE WOOD FOLE	[ completed/no problems	Total # of Attachments:
40677795 (NC)	[ ]completed/new finding(s)	]
TENT DOGS	[ ]pre-existing cond chked	
1	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015808	
38.423095000000		
-121.8445180000		
006/143 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40592636	[ ]completed/new finding(s)	
PRI POST	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015807	
38.423746000 <b>000</b>		
-121.8439690000		
006/144 SINGLE WOOD POLE		Total # of Attachments:
40612583	[ ]completed/new finding(s)	
T=1 (c)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015806	
38.424281000000		
-121.8434960000		
006/145 SINGLE WOOD POLE		Total # of Attachments:
40874395	[ ]completed/new finding(s)	
TRT POST	[ ]pre-existing cond chked	
-(-(c)	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015805	
38.424856000000		
-121.8430110000		
006/146 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40869021	[ ]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
1 SV 1	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015804	
38,425220000000		
-121.8426630000	-	

Page 19

Date Inspected : _

Inspector Name : Cooper

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order

: 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		-12-,
Access:		
HOST Tech ID/Equip #:	Notes	J
Lat:		
Long:		
006/147 SINGLE WOOD POLE	Marmlohad/	Imperation of the control of the con
40823482	completed/no problems	Total # of Attachments:
TRI POST	[ ]completed/new finding(s)	
SV	[]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015803	
38.425859000000		
-121.8427540000		
006/148 SINGLE WOOD POLE	/ completed/no problems	Total # of Attachments:
40825165 PRI FOST (e)	[ ]completed/new finding(s)	
EXT. F037	[ ]pre-existing cond chked	
· ·	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015802	
38.426277000000		
-121.8423740000		
005/149 SINGLE WOOO POLE	Completed/no problems	Total # of Attachments:
40767508	[]completed/new finding(s)	" - · · · · · · · · · · · · · · · · · ·
TRI POST	[ ]pre-existing cond chked	
	[ ] not inspetd this patrol	
	Notes: '02 Survey: C015801	
38.426892000000	Notes: 102 Survey: C015801	
-121.6418250000		
006/150 SINGLE WOOD POLE		
		Total # of Attachments:
40759924	[ ]Completed/new finding(s)	
ANGLE 30 80 DEGREES	[ ]pre-existing cond chked	
7-1(6)	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015800	
38.427153000000		
-121.9415540000		
006/151 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40665527	[ ]completed/new finding(s)	
72 FOST (C)	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015799	
38.428009000000		
-121.8408650000		i i
006/152 SINGLE WOOD POLE		Total # of Attachments:
40677791	[]completed/new finding(s)	TOTAL W OT RECOGNISHES:
TRI POST	[]pre-existing cond chked	
, ,	[ ]not inspetd this patrol	· ·
38.428668000000	Notes: '02 Survey: C015798	
-121.8402470000		
006/153 SINGLE WOOD POLE		Total # of Attachments:
40599394	[]completed/new finding(s)	
TRI POST (C)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015797	
38.429277000000		
-121.8397300000		
006/154 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40874407 - + \ (4)	[]completed/new finding(s)	
PRI POST ()	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015796	
38.429889000000	-	
-121.8392060000		

Page 20

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Inspector Name : Cooper

Date Inspected : 3-26-12

Desc of Tech ID	Inspection Result	
Equip #	BCCCTOH KESUIC	Attachments #
Framing Config		Attachment Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	1	
Long:	1.	
006/155 SINGLE WOOD POLE		Total # of Attachments:
40875459	[]completed/new finding(s)	Total # Of Accachments:
TRI POST	[ ]pre-existing cond chked	
T-1(c)	[ ]not inspctd this patrol	
,	Notes: '02 Survey: C015795	
38.430476000000	-	
-121.8386560000		
006/156 SINGLE WOOD POLE	/ ]completed/no problems	Total # of Attachments:
40816643 TRI POST	[ ]completed/new finding(s)	
THI POST (C)	[ ]pre-existing cond chked	
• •	[]not inspctd this patrol	
38.431163000000	Notes: '02 Survey: C015794	
-121.8381010000		
006/157 SINGLE WOOD POLE		<del></del>
40006160	completed/no problems	Total # of Attachments:
TRI POST	[ ]dompleted/new finding(s)	
ZHP	[]pre-existing cond chked	
	[ ]not inspctd this patrol Notes: '02 Survey: C015793	
38.431720000000	Modes: 102 Survey: C015793	
-121.8378210000		
007/158 SINGLE WOOD POLE	//completed/no problems	Total # of Attachments:
40759677	[]completed/new finding(s)	Total # Of Attachments:
TRI POST	[ ]pre-existing cond chked	
T-((c)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015792	
38.432287000000	_	
-121.8370920000		
007/159 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
10759922 T-\(c)	[ ]completed/new finding(s)	
TOST \ —\\	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
88.432839000000	Notes: '02 Survey: C015791	
121.8365620000		
07/160 SINGLE WOOD POLE	(A complete )/	
0657549	completed/no problems	lotal # of Attachments.
RI POST T-V(c)	[ ]completed/new finding(s) [ ]pre-existing cond chked	
, , ,	[ ] not inspctd this patrol	
	Notes: '02 Survey: C015790	
8.433496000000	22 Sarvey: C013/90	
121.8360410000		
07/161 SINGLE WOOD POLE	Completed/no problems T	otal # of Attachments:
0695456	[ ]completed/new finding(s)	" " " " " " " " -
T-1(c)	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015789	
3.434102000000		
121.8355320000		
07/162 SINGLE WOOD POLE	Completed/no problems   T	otal # of Attachments:
0592635	[ ]completed/new finding(s)	
T POST (C)	[ ]pre-existing cond chked	
(-)	[ ]not inspctd this patrol	
434683000000	Notes: '02 Survey: C015788	
21.8349950000		

Page 21

Inspector Name : Coopen Date Inspected : 3-26-12

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

: 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		1E-1/ 011201 1172040
Access:		
HOST Tech ID/Equip #:	Notes	<u></u>
Lat:		
Long:		
007/163 SINGLE WOOD POLE	completed/no problems	(makes) the Court of
40612586	[]completed/new finding(s)	Total # of Attachments:
TRI POST [-\ (N/C)	I Jeompleted/new finding(s)	
1 ((%)6)	[]pre-existing cond chked	
	[ ]not inspctd this patrol	
38.435285000000	Notes: '02 Survey: C015787	
<del></del>		
-121.8344840000		
007/164 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0868357	[ ]completed/new finding(s)	
PT POST	[ ]pre-existing cond chked	
T-(c)	[ ]not inspetd this patrol	
· ( )	Notes: '02 Survey: C015786	<u></u>
8.43583000000		
121.8339210000		
07/165 SINGLE WOOD POLE		
007/165 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
	[ ] completed/new finding(s)	
T-16)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015785	
8.436417000000		
121.8333890000		
07/166 SINGLE WOOD POLE	I I governous to the second	
0823484	[ ]completed/no problems	Total # of Attachments:
I Post	cmpleted/new finding(s)	
1-101	[ ]pre-existing cond chked	
7-10	[ ] not inspctd this patrol	tals cut at All Stule
	Notes: '02 Survey: C015784	Pole cut AT 6/L - Stub
3.437001000000		(a Me N >
.21.8328370000		
07/167 SINGLE WOOD POLE	completed/no problems	77
0825163	[]completed/new finding(s)	Total # of Attachments:
T POST		
(°)/-T	[ ]pre-existing cond chked	
4 4/	[ ]not inspctd this patrol	
	The part of the part of	
	Notes: '02 Survey: C015783	
.437644000000	Notes: '02 Survey: C015783	
.437644000000	Notes: '02 Survey: C015783	
.437644000000	Notes: '02 Survey: C015783	Fotal # of Attachmonta
.43764400000 21.8323600000 7/168 SINGLE WOOD FOLE	Notes: '02 Survey: C015783	Fotal # of Attachments:
.437644000000 21.8323600000 7/168 SINGLE WOOD POLE 767510	Notes: '02 Survey: C015783  [Completed/no problems I completed/new finding(s)]	Fotal # of Attachments:
.437644000000 21.8323600000 7/168 SINGLE WOOD POLE 767510	Notes: '02 Survey: C015783  [ ] Completed/no problems [ ] Jompleted/new finding(s) [ ] pre-existing cond chked	Fotal # of Attachments:
.43764400000 21.8323600000 7/168 SINGLE WOOD POLE 767510	Notes: '02 Survey: C015783  [Completed/no problems [Jcompleted/new finding(s)] []pre-existing cond chked []not inspetd this patrol	Fotal # of Attachments:
.43764400000 21.8323600000 7/168 SINGLE WOOD POLE 767510	Notes: '02 Survey: C015783  [ ] Completed/no problems [ ] Jompleted/new finding(s) [ ] pre-existing cond chked	Fotal # of Attachments:
.43764400000 21.8323600000 7/168 SINGLE WOOD FOLE 767510 1 POST (E)	Notes: '02 Survey: C015783  [Completed/no problems [Jcompleted/new finding(s)] []pre-existing cond chked []not inspetd this patrol	Fotal # of Attachments:
.43764400000 21.8323600000 7/168 SINGLE WOOD FOLE 767510 1 POST (E)	Notes: '02 Survey: C015783  [Completed/no problems [Jcompleted/new finding(s)] []pre-existing cond chked []not inspetd this patrol	Fotal # of Attachments:
.43764400000 21.8323600000 7/168 SINGLE WOOD POLE 767510 	Notes: '02 Survey: C015783  [ ] Completed/no problems [ ] Johnpleted/new finding(s) [ ] pre-existing cond chked [ ] Inot inspetd this patrol Notes: '02 Survey: C015782	
.43764400000 21.8323600000 7/168 SINGLE WOOD POLE 767510 1 POST  .438275000000 21.8318580000 7/169 SINGLE WOOD POLE 768151	Notes: '02 Survey: C015783  [Completed/no problems [Jcompleted/new finding(s) [Jpre-existing cond chked [Jnot inspetd this patrol Notes: '02 Survey: C015782	Fotal # of Attachments:
.43764400000 22.8323600000 7/168 SINGLE WOOD POLE 767510 1 POST  .438275000000 21.8318580000 7/169 SINGLE WOOD POLE 168151	Notes: '02 Survey: C015783  [ Completed/no problems	
43764400000 21.8323600000 7/168 SINGLE WOOD POLE 7/168 SINGLE WOOD POLE 7/169 SINGLE WOOD POLE 68151	Notes: '02 Survey: C015783  [ ] Completed/no problems [ ] Jcompleted/new finding(s) [ ] Ipre-existing cond chked [ ] Inot inspetd this patrol Notes: '02 Survey: C015782  [ ] Completed/no problems [ ] Completed/new finding(s) [ ] Ipre-existing cond chked	
.43764400000 21.8323600000 7/168 SINGLE WOOD POLE 767510	Notes: '02 Survey: C015783  [Completed/no problems	
43764400000 21.8323600000 7/168 SINGLE WOOD POLE 767510	Notes: '02 Survey: C015783  [ ] Completed/no problems [ ] Jcompleted/new finding(s) [ ] Ipre-existing cond chked [ ] Inot inspetd this patrol Notes: '02 Survey: C015782  [ ] Completed/no problems [ ] Completed/new finding(s) [ ] Ipre-existing cond chked	
438275000000  438275000000  1.8318580000  /169 SINGLE WOOD POLE  68151  FOST  438829000000	Notes: '02 Survey: C015783  [Completed/no problems	
438275000000  438275000000  21.8323600000  7/168 SINGLE WOOD POLE  7/67510  438275000000  21.8318580000  7/169 SINGLE WOOD POLE  68151  FOST  438829000000  1.83129000000	Notes: '02 Survey: C015783  [Completed/no problems	
.43764400000 21.8323600000 7/168 SINGLE WOOD POLE 767510 1 POST 21.8318580000 7/169 SINGLE WOOD POLE 768151 760ST 438829000000 1.8312900000	Notes: '02 Survey: C015783  [   Completed/no problems   I   Completed/new finding(s)	otal # of Attachments:
.43764400000 21.8323600000 7/168 SINGLE WOOD POLE 767510 1 POST  .438275000000 21.8318580000 7/169 SINGLE WOOD POLE 768151  POST  .438829000000 21.8312900000 21.8312900000	Notes: '02 Survey: C015783  [Completed/no problems I completed/new finding(s) I lpre-existing cond chked I lnot inspetd this patrol Notes: '02 Survey: C015782  [Completed/no problems I completed/new finding(s) I lpre-existing cond chked I lnot inspetd this patrol Notes: '02 Survey: C015781	
.43764400000 21.8323600000 7/168 SINGLE WOOD POLE 767510 1 POST .438275000000 21.8318580000 7/169 SINGLE WOOD POLE 688151 FOST .438829000000 21.8312900000 21.8312900000 7/170 SINGLE WOOD POLE	Notes: '02 Survey: C015783  [Completed/no problems I completed/new finding(s) I lpre-existing cond chked I lnot inspetd this patrol Notes: '02 Survey: C015782  [Completed/no problems I completed/new finding(s) I lpre-existing cond chked I lnot inspetd this patrol Notes: '02 Survey: C015781  [Completed/no problems I completed/no problems I loompleted/no problems I loompleted/no problems I loompleted/new finding(s)	otal # of Attachments:
.43764400000 21.8323600000 7/168 SINGLE WOOD POLE 767510 1 POST (c) .438275000000 21.8318580000 7/169 SINGLE WOOD POLE 768151 1 POST (c) 438829000000 21.8312900000 7/170 SINGLE WOOD POLE 665523 POST	Notes: '02 Survey: C015783  [Completed/no problems	otal # of Attachments:
.437644000000 21.8323600000 7/168 SINGLE WOOD POLE 767510 I POST  .438275000000 21.8318580000 7/169 SINGLE WOOD POLE 768151 I FOST  .438829000000 21.8312900000 7/170 SINGLE WOOD POLE 7655523	Notes: '02 Survey: C015783  [Completed/no problems	otal # of Attachments:
.437644000000 21.8323600000 7/168 SINGLE WOOD POLE 767510 I POST  .438275000000 21.8318580000 7/169 SINGLE WOOD POLE 768151 I FOST  .438829000000 21.8312900000 7/170 SINGLE WOOD POLE 7655523	Notes: '02 Survey: C015783  [Completed/no problems	otal # of Attachments:

Inspector Name: Cooper Date Inspected: 3-26-12

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567

: 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	-	Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	110000	
Long:		!
007/171 SINGLE WOOD POLE		
	leampleted/no problems	Total # of Attachments:
40677787	[]completed/new finding(s)	
TRE POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015779	
38.440248000000		
-121.8300320000		
007/172 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40599396	[ ]completed/new finding(s)	
THE FOST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015778	
38.441010000000		
-121.8293300000		
007/173 SINGLE WOOD POLE	Nompleted/no problems	Total # of Attachments: 2
40869019		CABL-UNKNOWN 1; DIST-0310456 1
mm# none	[]pre-existing cond chked	CABI-ONAMONN 1; DIS1*0310456 1
T-1(e)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015777	
38.441857000000		
-121.8286020000		
007/174 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40816641	[]completed/new finding(s)	DIST-0310456 1
Z-1(c)	[]pre-existing cond chked	
7-110)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015776	
38.442391000000		
-121.8280890000		
007/175 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40817764	[]completed/new finding(s)	
TRI POST.	[ ]pre-existing cond chked	
(C )	[]not inspctd this patrol	
てい(ら)	Notes: '02 Survey: C015775	
38.44298000000		
-121.8275790000		
007/176 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40759675	[] completed/new finding(s)	
FIELD SWITCH STRUCTURE	[ ]pre-existing cond chked	
FIEDD SWITCH STRUCTURE		TO TO TO A I I
	[ ]not inspctd this patrol	2 Dug out Buries Dist Aucher pal
	Notes:	
38.443565000000		
-121,8270230000	/_	
007/177 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40768160	[ ]completed/new finding(s)	
T-1(≰)	[ ]pre-existing cond chked	
-(-(5)	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015773	
38.444259000000		
-121.8263940000		
007/178 SINGLE WOOD POLE SW 29	completed/no problems	Total # of Attachments:
41122282 Dixou Sub	[]completed/new finding(s)	
447-519	[ ]pre-existing cond chked	
	[] not inspctd this patrol	T V
	Notes:	
38.444871000000		
-121.8259300000		

Page 23

Inspector Name : __ Date Inspected : 3-26-12

Funct Loc: ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		Type/owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
008/179 TUBULAR STEEL POLE	[ ]completed/es	
40665506 4771CE	[]completed/no problems	Total # of Attachments:
DOUBLE VERTICAL	recompleted/new finding(s)	
VIIII VIIII VIII	[ lpre-existing cond chked	1 SOLTED COUN'S
	[] not inspetd this patrol	
38.445041000000	Notes: '02 Survey: C015404	DELETE DUPLICATE ASSET
-121.8258320000	STRUCTURE IS FIELD	SWITCH STRUCTURE
008/180 CERAMIC INSULATOR	No need for separate	e pole record
42572564	completed/no problems	Total # of Attachments:
harrice	[ ]pre-existing cond chked	
008/181 41195901	[ ]not inspetd this patrol	
	Notes:	
38.445685000000		
-121.8257870000		
008/181 CERAMIC INSULATOR	Teempleted/no problems	Total # of Attachments:
42572565	[ ]completed/new finding(s)	
LACTICE	[ ]pre-existing cond chked	•
	[ ]not inspetd this patrol	
008/182 41195916	Notes:	
38.446327000000		
-121.8258070000		
008/182 CERAMIC INSULATOR	completed/no problems	Total # of Attachments:
40696834	(   completed/new finding(s)	" or verdefinence:
TELD SWITCH STRUCTURE	[ ]pre-existing cond chked	
LATTICE	[ ]not inspetd this patrol	
	Notes: OUTSIDE SUB	
38.447192000000		
-121.8258000000		
008/183 CERAMIC INSULATOR	Completed/no problems	Total # of Attachments:
10626049	[]completed/new finding(s)	- OF MCLACHMETTES:
DOUBLE VERTICAL LATTICE	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
008/184 40868986	Notes:	
8.448030000000		
121.8257780000		
08/184 CERAMIC INSULATOR	completed/no problems T	Potal # of Jan.
0639666	[]completed/new finding(s)	Total # of Attachments:
OUBLE VERTICAL	[]pre-existing cond chked	
S) is the	[ ]not inspetd this patrol	
08/185 40816607	Notes:	
8.448819000000		
121.8257700000		
08/185 CERAMIC INSULATOR	Completed/no problems   T	otal WE. V.
0898825	[]completed/new finding(s)	otal # of Attachments:
OUBLE VERTICAL CAROLICE	[ ]pre-existing cond chked	
CAT-CLOS	[ ]not inspetd this patrol	ł
08/186 40819575	Notes:	
3.449642000000	NOCES:	
L21.8257480000		
08/186 CERAMIC INSULATOR		
0893484	completed/no problems To	otal # of Attachments:
	[]completed/new finding(s)	1
DUBLE VERTICAL (Queculia (CE)	[ ]pre-existing cond chked	
08/187 40767512	[]not inspctd this patrol	
.450472000000	Notes:	
21.8257190000		

Page 24

Inspector Name : COOPER

Date Inspected : 3-26-12

Funct Loc: ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	
Equip #	TINSAN TOTA SAGET	Attachments #
Framing Config		Attachment Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	Notes	
Long:		•
008/187 CERAMIC INSULATOR		<i>r</i>
40842416	[ ]completed/no problems	Total # of Attachments:
40842416	[   completed/new finding(s)	
DOUBLE VERTICAL ATTICAL	pre-existing cond chked	
Ogra	[ ] not inspetd this patrol	Red T. 1 Q. I.
008/188 40768156	Notes:	Replace Insulations - Pins on lattice
38.45129900000		OU 1-2 405
121.8245910000		•
008/188 CERAMIC INSULATOR	[ completed/no problems	Total # of Attachments:
10848018	[]completed/new finding(s)	TOTAL # DI Attachments:
DOUBLE VERTICAL LATITUS	[ ]pre-existing cond chked	
<b>V4</b> •	[ ]not inspetd this patrol	
008/189 40665509	Notes:	
8.451270000000		
121.8236970000		
08/189 CERAMIC INSULATOR	[ ] complete at	
0798260	[]completed/no problems	Total # of Attachments:
OUBLE VERTICAL		
1 SCTIO	Spre-existing cond chked	0 1 1
08/190 40681696	[ ]not inspetd this patrol	KorelAer Tusulating Die
	Notes: MONITOR BOTTOM TIE W	TRE FUND ON AVIOR
8.451284000000	1 .	Replace Insulations pins on writer OK 1-2419
121.8226480000	<u> </u>	UK 1- C718
08/190 CERAMIC INSULATOR		Total # of Attachments:
0799667	[ ]completed/new finding(s)	*********************************
DUBLE VERTICAL A (()	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
08/191 40592598	Notes:	
3.451516000000		
.21.8213130000		
9/191 CERAMIC INSULATOR		De de 2 H
696838	[]completed/new finding(s)	Potal # of Attachments:
UBLE VERTICAL ATTICE	[ ]pre-existing cond chked	
F-1 (100	last income cond chied	
8/192 40601216	[ ]not inspetd this patrol	
.451502500000	Notes:	
21.8203355000		
<del></del>		
9/192 LATTICE STEEL POLE /	completed/no problems   T	otal # of Attachments:
19391/	[ ]completed/new finding(s)	
1	[ ]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes:	
451473000000		
21.8192910000		
7/193 SINGLE WOOD POLE	completed/no problems To	
13009	[]completed/new finding(s)	otal # of Attachments:
PIN ARM	[ Inve-existing and in in	
	[ ]pre-existing cond chked	
	[]not inspetd this patrol	
450000000000000000000000000000000000000	Notes: '02 Survey: C015388	
45 20 40 00 00 0		
1.8187680000		
452090000000 1.8187680000 /194 SINGLE WOOD POLE	completed/no problems To	Otal # of Attachments, 1
1.8187680000 /194 SINGLE WOOD POLE 13008	l  completed/new finding(s) DI	otal # of Attachments: 1
1.8187680000 /194 SINGLE WOOD POLE 13008	[ ]completed/new finding(s) Dr	otal # of Attachments: 1 EST-0310456 1
1.8187680000 /194 SINGLE WOOD POLE 13008 PIN ARM	[ ]completed/new finding(s) DI [ ]pre-existing cond chked	otal # of Attachments: 1 EST-0310456 1
1.8187680000 /194 SINGLE WOOD POLE 13008 PIN ARM	[ ] completed/new finding(s) Dr [ ] pre-existing cond chked [ ] not inspetd this patrol	otal # of Attachments: 1 EST-0310456 1
1.8187680000 /194 SINGLE WOOD POLE 13008 PIN ARM	[ ] completed/new finding(s) Dr [ ] pre-existing cond chked [ ] not inspetd this patrol [ ] lotes: '02 Survey: C015387	SPOTTLE ? ??

Page 25

Inspector Name : Cooper

Date Inspected : 3-20-12

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
009/195 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40913007	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015386	
38.453274000000	MONITOR OLD POLE	
-121.8176840000	110111111111111111111111111111111111111	
009/196 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40913006	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015385	
38.453867000000	Notes: 02 adrivey: C019389	
-121.8171580000		
009/197 SINGLE WOOD POLE	Vacamaloted/no analyl	manal H of Street
40913005	sompleted/no problems	Total # of Attachments:
	[ ] completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015384	
38.45444000000	MONITOR OLD SHELL R	OTTEN POLE
-121.8166390000		
009/198 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40913004	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015383	
38.455074000000		
-121.8160870000		
009/199 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40913003	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015382	
38.455681000000		
-121.8155450000		
009/200 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40913002	[ ]completed/new finding(s)	
TRI PI <b>N ARM</b>	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015381	
38.456252000000		
-121.8150580000	The second second	
009/201 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
10913001	[ ] completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015380	
38.45684700000	Locob. V2 Durvey: Co13380	
-121.8145250000		
109/202 SINGLE WOOD POLE		Total # of Attachments:
10868353	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT;LINE TR	[]not inspctd this patrol	
A. A. C. T. A. C.	Notes: '02 Survey: C015379	
88.457415000000		
121.8140040000		

Inspector Name : _ Cooper Date Inspected : _

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		725-/ UNICE Hibled
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	İ	
Long:		
009/203 SINGLE WOOD POLE	[]completed/no problems	material H. Constitution
10869017	[]completed/new finding(s)	Total # of Attachments:
TRI PIN ARM	pre-existing cond chked	<b>'</b>
	[]not inspctd this patrol	0 -
	Notes: '02 Survey: C015378	REFRAME T-1
8.457961000000	Modes: 02 Survey: C015378	
121.8134800000		
09/204 SINGLE WOOD POLE		
0816639 /	completed/no problems	Total # of Attachments:
RI PIN ARM	[ ]completed/new finding(s)	
ALL LIX MIT	[ ]pre-existing cond chked	[
	[ ]not inspetd this patrol	
8.45856500000	Notes: '02 Survey: C015377	
	MONITOR SHELL ROTTE	N POLE
121.8129390000		
09/205 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0817762	(   completed/new finding(s)	
RI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015376	
8.459217000000	-	
121.8123650000		
09/206 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
759673	[ ]completed/new finding(s)	TOTAL W OF ACCACHMENTS:
RI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015375	
3.459773000000	MONITOR SHELL ROTTEN	I DOLD
21.8118830000	A STATE OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROLL OF THE ROL	V FOLE
9/207 SINGLE WOOD POLE	Geompleted/no problems	Total # of Attachments:
759920	[ ]completed/new finding(s)	Total # Of Actachments:
ri pin arm 🗸	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015374	
.460414000000		
21.8113610000	MONITOR OLD SHELL RO	TTEN POLE
9/208 SINGLE WOOD POLE	->-	
657546 —	Completed/no problems	Total # of Attachments:
I PIN ARM	[]completed/new finding(s)	
L FIN ARM	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015373	
461020000000	321 1.	
1.8107680000	TOK HAS WO	OU STUB. Some CROWN ROT
/209 SINGLE WOOD POLE	[ completed/no problems	Total # of Attachments:
95635	[ ]completed/new finding(s)	
PIN ARM TRAMP	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015372	The second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second secon
461564000000		
1.8102500000		
210 SINGLE WOOD POLE	// completed/no problems	Pot-3 # of ptu-si
86217	[]completed/new finding(s)	Total # of Attachments:
7051 (He)		
	[ ]pre-existing cond chked	
- 4	[ ]not inspctd this patrol Notes: '02 Survey: C015371	
462188000000	noces: -02 Survey: CU15371	

Page 27

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

: 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Inspector Name : Cooper

Date Inspected : 3-20

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		weachment Type/Owner Elsted
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	1-1-1-1	
Long:		
010/211 SINGLE WOOD POLE		Total # of Attachments:
40677783	[]completed/new finding[s]	TOTAL # OF ACCAMENCS:
TRI 1097	[]pre-existing cond chked	
1-10	[]not inspetd this patrol	
	Notes: '02 Survey: C015370	
38.462774000000	1	
-121.8091830000		
010/212 SINGLE WOOD POTE	Completed/no problems	Total # of Attachments:
40599432	[ ]completed/new finding(s)	
TRI DIN AND	[ ]pre-existing cond chked	
TPA	[ ]not inspetd this patrol	
11.	Notes: 102 Survey: C01E360	
38.463343000000	MONITOR OLD SHELL R	OTTEN POLE - MINOR-FIRE DAMSE
-121.8087330000		). I HACKELING TOWNSE
010/213 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40601251	[]completed/new finding(s)	
TRI DOCT	[ ]pre-existing cond chked	
T-1(NC)	[ ]not inspetd this patrol	
, ,	Notes: '02 Survey: C015368	
38.463984000000		
-121.8081210000		
010/214 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40868351	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015367	
38.464557000000	Minou Y	2
-121.8076120000		<del></del>
010/215 SINGLE WOOD POLE		Total # of Attachments:
40875536 TRI POST T-1(C)	[ ]completed/new finding(s)	
TRI POST (-10)	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
38.465138000000	Notes: '02 Survey: C015366	
-121.8070940000		
010/216 SINGLE WOOD POLE 40823512		Total # of Attachments:
TRI POST ( (MIC)	[ ]completed/new finding(s)	
(-101-)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
38.465725000000	Notes: '02 Survey: C015365	
-121.8065450000		
010/217 SINGLE WOOD POLE		
40817760	[] completed/new finding(s)	Total # of Attachments:
	[ ]pre-existing cond chked	
T-I(NC)	[]not inspctd this patrol	
( )	Notes: '02 Survey: C015364	
38.466282000000	notes: 102 survey: C015364	
-121.8061030000		
010/218 SINGLE WOOD POLE	Completed/no problems	mahal Hafari
10767542	[ ] completed/no problems	Total # of Attachments:
T-1 (N/C)	[]pre-existing cond chked	
(-(()))	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015363	
88.466757000000		
121.8057030000		

Page 28

Inspector Name : Cooper Date Inspected: 3-20-12

			Detailed Ground Inspection
Desc of Tech ID	Inspection Result	Attachments #	
Equip # Framing Config		Attachment Type/Owner	Listed
Access:			
HOST Tech ID/Equip #:	Notes		
Lat: Long:			
010/219 SINGLE WOOD POLE			i i
40768227	Sompleted/no problems	Total # of Attachments: 1	
TRI DIN SEM (A/C)	[ ]completed/new finding(s)	DIST-0310456 1	II.
TEL DEN ARM (NC)	[]pre-existing cond chked		1/
, ,	[]not inspetd this patrol		_ [/
38.467105000000	Notes: '02 Survey: C015362		
-121.8053710000	1.		<i>  </i>
010/220 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:	
10665549	[ ]completed/new finding(s)	rotal # of Attachments:	
CAIC)	[ ]pre-existing cond chked		i
(AIC)	[ ]not inspetd this patrol		
	Notes: '02 Survey: C015361		
8.467675000000	17-1 10 Barrey, Colbset		
121.8048710000			
10/221 SINGLE WORD POLE	I mpleted/no problems	Total # of attachment	
0677779	[]completed/new finding(s)	TOTAL # OI Attachments:	
RI PIN ARM	[ ]pre-existing cond chked		
	[ ]not inspetd this patrol		
	Notes: '02 Survey: C015360		
8.468263000000			
121.8043070000	TOLE HAS WOOD	Stule	
10/222 SINGLE WOOD POLE	[   sompleted/no problems	Total # of Attachments:	
0592633	[ ]completed/new finding(s)	- " "ecocumentes;	
RIANGLE POST 70	[ ]pre-existing cond chked		file
~ ( A( )	[ ]not inspetd this patrol		
	Notes: '02 Survey: C015359		
8.468814000000			
121.8038380000		Acres to a second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second secon	
10/223 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:	
1501248 WHICH FOST 70T-1 NC	[ ]completed/new finding(s)		17.
POST 70°	[ ]pre-existing cond chked		1.3
	[ ]not inspetd this patrol		
.469232000000	Notes: '02 Survey: C015358		
.21.8035090000			
0/224 SINGLE WOOD POLE	Tampleted/		
0874447	[ ] completed/no problems	Total # of Attachments:	
I PIN ARM	[]completed/new finding(s)		
	[ ]pre-existing cond chked		
	[ ]not inspctd this patrol Notes: '02 Survey: C015357		
.469693000000	2 Survey: C015357		
21.8030690000			
0/225 SINGLE WOOD POLE	[ ]completed/no problems [	otal # of Attachments:	
875499	[] completed/new finding(s)	Cocal # OF Attachments:	
THELE POST M(HC)	pre-existing cond chked		
	[] not inspetd this patrol	LEGANINE DI	
	Notes: '02 Survey: C015356	LEADING PK	
470218000000			
21.8026090000	RATES Pole		
1/226 SINGLE WOOD POLE		otal # of Attachments:	
315637	[ ]completed/new finding(s)	" " " " " " " " " " " " " " " " " " "	
(-1000 (e)	pre-existing cond chked		
,	[ ]not inspetd this patrol	Lawine Pole	
	Notes: '02 Survey: C015355	Lawing Pole	
470778000000			
1.8021100000			

Page 29

Inspector Name : Cooper Date Inspected : _

Funct Loc: ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	1
Lat: Long:		
010/227 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40825232	[   completed/new finding(s)	
TRI PIN ARM	pre-existing cond chked	
	[ ]not inspetd this patrol	LEANING POLY CHAS 'C' Truss INSTALL
38.47140300000	Notes: '02 Survey: C015354	1 4 7 1100 C 1000 X1020111
-121.8015520000 010/228 SINGLE WOOD POLE		
40767544	completed/no problems	Total # of Attachments:
	[ ]completed/new finding(s)	
TEL DIN ARM ( ) (NE)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
38.471970000000	Notes: '02 Survey: C015353	
-121.8010200000	,	
010/229 SINGLE WOOD POLE		
107229 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
	[ ]completed/new finding(s)	
BI POST (-/(N/C)	[ ]pre-existing cond chked	
, ,	[ ]not inspetd this patrol	
8.472500000000	Notes: '02 Survey: C015352	
121.8004750000		
10/230 SINGLE WOOD POLE		
0665552	completed/no problems	Total # of Attachments:
NE POST	[ ]completed/new finding(s)	
1000	[ ]pre-existing cond chked	
1	[ ]not inspetd this patrol	
9.473167000000	Notes: '02 Survey: C015351	
L21.7999940000		
10/231 SINGLE WOOD POLE		Tue_
1599996	completed/no problems	Total # of Attachments:
CAME SOURCE DEAD END	[ ]completed/new finding(s)	
CAUL SCORES SAD	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
47370200000	Notes: '02 Survey: C015350	
21.7995160000		
0/232 SINGLE WOOD POLE		
592632 MOOD POLE	completed/no problems	Fotal # of Attachments:
I PIN ARM	[ ]completed/new finding(s)	
T TYN WILL	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
47477000000	Notes: '02 Survey: C015349	
.474328000000		
21.7989110000		
1/233 SINGLE WOOD POLE	completed/no problems   T	otal # of Attachments:
599434	[ ]completed/new finding(s)	
FILL ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
/	Notes: '02 Survey: C015347	
474971000000		İ
21.7983770000		
./234 SINGLE WOOD POLE	Completed/no problems To	otal # of Attachments:
01245	l completed/new finding(s)	
ANGLE POST 70	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	1
	Notes: 02 Survey: C015346	
475577000000		
1.7978540000		

Page 30

Inspector Name : Date Inspected :

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	THE POST OF THE PARTY	Attachment Type/Owner Listed
Framing Config		
Access:		
	W	
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
011/235 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40874427	[ ]completed/new finding(s)	1
TOTANGLE POST 30	[ ]pre-existing cond chked	
140	[ ]not inspetd this patrol	
1	Notes: '02 Survey: C015345	i
38.476110000000		
-121.7973600000		
011/236 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40869015	[ ] completed/new finding(s)	
TRIANGLE POST 70 (UC)	[ ]pre-existing cond chked	
,,,,,,	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015344	
38.476740000000		
-121.7968030000		
011/237 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40823514	[]completed/new finding(s)	•
_	[]pre-existing cond chked	
T-I (NC)	[] not inspetd this patrol	
1	Notes: '02 Survey: C015343	4 CIUTUED OF POLE CELLO
	· ·	
38.477324000000	NEW POLE	
-121.7962620000	, , , , , , , , , , , , , , , , , , ,	
011/238 SINGLE WOOD POLE	/Completed/no problems	Total # of Attachments:
40825234	[ ]completed/new finding(s)	
TRITANGED POST 70T-1 (N/C)	[ ]pre-existing cond chked	
\ \'\'\'\	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015342	
38.477929000000		
-121.7957100000	NEW HOLE.	
011/239 SINGLE WOOD POLE	NEW Pole.    Completed/no problems	Total # of Attachments:
40767568	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015341	<u> </u>
38.478470000000	MONITOR POLE - OLD	Cabac (ST ) - A con se
-121.7952260000	<b>5</b>	ceour, slight Arm Kut
011/240 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
	[]completed/new finding(s)	,
40752000 TRY DIN AND T-1 (NC)	[]pre-existing cond chked	
1-1 (MC)	[]not inspetd this patrol	
	Notes: '02 Survey: C015340	LEANING MONITOR ONLY
39 47007000000	noces. 02 burvey; col3340	DESCRIPTION OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF
38.479079000000		
-121.7946570000	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
011/241 SINGLE WOOD POLE	dcompleted/no problems	Total # of Attachments:
40665553	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015339	LEANING
38.479675000000		
-121.7941710000		
011/242 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40695543 TPA TRAMO	[ ]completed/new finding(s)	
TRAMP DOUBLE DEAD END	Virg-existing cond chked	
	[] not inspctd this patrol.	& LEANING POTE - NO CHANGE
	Notes: 102 Survey: C015338	LEANING
38.480309000000		
-121.7936190000		

Page 31

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567

PATR/INSP 60067 DIXON-VACA #2+

Inspector Name : Cores Date Inspected : 3.

Detailed Ground Inspections

Medium Impact

Desc of Tech ID Inspection Result Attachments # Equip # Attachment Type/Owner Listed Framing Config Access: HOST Tech ID/Equip #: Notes 011/243 SINGLE WOOD POLE []completed/no problems Total # of Attachments: 40592630 [ ]completed/new finding(s) Here-existing cond chked * heavive [ ]not inspctd this patrol Notes: '02 Survey: C015337 LEANING, MINOR 38.48086300000 -121.7931050000 011/244 SINGLE WOOD POLE completed/no problems Total # or Attachments: []completed/new finding(s) TRI FIN ADM (~ 1 (N/c) [ ]pre-existing cond chked [ ]not inspetd this patrol Notes: '02 Survey: C015336 LEANING, MINOR 38.483472000000 -121.7925460000 011/245 SINGLE WOOD POLE [ ]completed/no problems Total # of Attachments: 40868349 { ]completed/new finding(s) TRIANGLE POST PH (NC pre-existing cond chked ROTTEN F [ ]not inspctd this patrol Notes: '02 Survey: C015335 LEANING, MINOR 38.482049000000 -121.7920590000 011/246 SINGLE WOOD POLE Completed/no problems | Total # of Attachments: 40869014 [ ]completed/new finding(s) TRI PIN ARM [ ]pre-existing cond chked [ ]not inspctd this patrol Notes: '02 Survey: C015334 38.482653000000 -121.7915160000 011/247 SINGLE WOOD POLE completed/no problems Total # of Attachments: 40823516 [ ]completed/new finding(s) TRI PIN ARM [ ]pre-existing cond chked [ ]not inspctd this patrol Notes: '02 Survey: C015333 38.483252000000 -121.7909920000 011/248 SINGLE WOOD POLE | completed/no problems Total # of Attachments: 40817758 [ ]completed/new finding(s) [ ]pre-existing cond chked [ ]not inspctd this patrol Notes: '02 Survey: C015332 38.483863000000 -121.7904560000 011/249 SINGLE WOOD POLE completed/no problems Total # of Attachments: 40767546 [ ]completed/new finding(s) [ ]pre-existing cond chked [ ]not inspctd this patrol Notes: '02 Survey: C015331 38.484438000000 -121.7899360000 011/250 SINGLE WOOD POLE Completed/no problems Total # of Attachments: 40759917 [ ]completed/new finding(s) [ ]pre-existing cond chked [ ]not inspctd this patrol Notes: '02 Survey: C015330 38.485043000000 -121.7894150000

Page 32

Inspector Name : Cooper Date Inspected : 3-4-12

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567

PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		Intraction Type/Owner Disced
Access:		
	· · · · · · · · · · · · · · · · · · ·	
HOST Tech ID/Equip #:	Notes	
Lat:	ļ	
Long:	1	
011/251 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40665589	[]completed/new finding(s)	
TRI PIN ARM		
IRI BIN ARM	upre-existing cond chked	\\\ - \\ - \\ - \\ - \\ - \\ - \\ - \\
	[ ] not inspctd this patrol	
	Notes: '02 Survey: C015329	
38.485624000000		<b>,</b>
-121.7889010000		
011/252 SINGLE WOOD POLE	[ sompleted/no problems	Total # of Attachments:
40677772	[]completed/new finding(s)	
THE POST T-1 (N/C)	[]pre-existing cond chked	
1-1 (N/C)	_ ~	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015328	
38.486218000000		
-121.7883740000		
011/253 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40599467	[   completed/new finding(s)	
TRIANGLE POST 20 1(1)	[]pre-existing cond chked	
1-1(N/C)		
· · · ·	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015327	
38.486798000000		
-121.7878480000	<b>)</b>	
012/254 SINGLE WOOD FOLE	completed/no problems	Total # of Attachments:
40665555	[ ]completed/new finding(s)	
TRIANGLE POST TO	[]pre-existing cond chked	
140		
_	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015326	
38.487055000000		
-121.7875900000		
012/255 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40695547 T-1 (N/C)	[ ]completed/new finding(s)	
1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	[ ]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C015325	
38.487393000000		
-121.7872930000		
012/256 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40586215	[ ]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
<b></b> - <b></b> - <b>/</b>	[ ]not inspctd this patrol	
70 (0-00-00-00-00-00-00-00-00-00-00-00-00-0	Notes: '02 Survey: C015324	· · · · · · · · · · · · · · · · · · ·
38.48799000000	DI 11 "0"	
-121.7867730000		<i>ড</i> S
012/257 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40601242	[ completed/new finding(s)]	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015323	
30 40053300000	Noces: 102 Survey: C013323	
38.488577000000		
-121.7862480000		
012/258 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40874454	[ ]completed/new finding(s)	
TRIVETE FOST TO THE	[ ]pre-existing cond chked	
「「「	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015322	
38.489092000000	Darvey: Corsszz	
	1	
-121.7858310000		

Inspector Name : Cooper Date Inspected : 3-5-12

Funct Loc : ETL.6740.POLE.WOOD

40.FOLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	THE DECLION KERGIC	
Framing Config		Attachment Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	ROTES	
Long:		
012/259 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40875501	[ ]completed/new finding(s)	
TRI POST- (-1C)	[ ]pre-existing cond chked	
1-16)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015321	
38.4896 <b>600</b> 00000		
-121.7853630000		
012/260 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40809775	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015320	
38.490263000000	2 Par AGA : COTP350	
-121.7847670000		
012/261 SINGLE WOOD POLE	Normal sheet /as a second 1	
40817756	[ Kcompleted/no problems	Total # of Attachments:
TRI PIN ARM	[ ]completed/new finding(s)	
ARE PER MEN	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015319	
38.490843000000		
-121.7842630000		
012/262 SINGLE WOOD POLE		Total # of Attachments:
40767548	[ ]completed/new finding(s)	
TRI PIN ARM TRAMP	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015318	
38.491489000000		
-121.7836860000		
012/263 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40759914	[ ]completed/new finding(s)	Total # Of Actaliments;
TRI PIN ARMI	[ ]pre-existing cond chked	
	[] not inspctd this patrol	
	Notice 102 Guerra Gas 5315	
38.492065000000	Notes: '02 Survey: C015317	ARM NG BOND BROKEN
-121.7831710000		
012/264 SINGLE WOOD POLE		Total # of Attachments:
10657545	[ ]completed/new finding(s)	l l
TRIANGLE POST 707 + (C)	[ ]pre-existing cond chked	
1.11	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015316	
88.492594000000	MONITOR OLD SHELL RO	T POLE
121.7826790000		
12/265 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
0660483	[ ]completed/new finding(s)	DIST-0310456 1
RI POST	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015315	
8.49294900000		
121.7823280000		
12/266 SINGLE WOOD POLE	I loomploted (%	
		Total # of Attachments:
.0592620	[ ] yompleted/new finding(s)	
	16 2	
	pre-existing cond chked	$\Theta \cup \Theta \cup \Theta \cup \Theta = \emptyset$
	pre-existing cond chked [ ] not inspetd this patrol	Pole Robber - Hollow Dram
RI PIN ARM	pre-existing cond chked not inspctd this patrol Notes: '02 Survey: C015314	Pole Ropher - Hollow Dron
10592629 PRI PIN ARM 18.493504000000 121.7817490000	pre-existing cond chked not inspctd this patrol Notes: '02 Survey: C015314 MONITOR OLD FOLE AND	POLE Rophes - Hollow Drom  XARM HAS OSMOSE STUD TAG.

Page 34

Inspector Name : COOPEK Date Inspected : 3-5-

Funct Loc : ETL. 6740. POLE. WOOD

60067 DIXON-VACA #2+-WOOD POLE

: 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	1	
012/267 SINGLE WOOD POLE	Completed/no problems	material distriction of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the se
10612717		Total # of Attachments:
IRI PIN ARM	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015313	
88.494063000000		
121.7811120000		
12/268 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0874429	[]completed/new finding(s)	
RI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015312	
8.494601000000	RE BOLT BOTTOM BRAC	
121.7805180000	THE PARTY OF THE PROPERTY OF THE PARTY OF TH	DONE ON DEC
	1	Indiana de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya del companya de la companya del companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de
12/269 SINGLE WOOD POLE	// completed/no problems	Total # of Attachments:
10869012	[]completed/new finding(s)	
RI PIN API / H(C)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015311	
8.495149000000		
121.7798880000		
12/270 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0816635	[ ]completed/new finding(s)	
RIANGLE POST 2011(A)	[]pre-existing cond chked	
14(6)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015310	
8.495573000000	Notes: 'UZ Sarvey: C015310	
121.7794470000		
12/271 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0825191	[ ]completed/new finding(s)	
OUR'S VERTICAL H (C)	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015309	
8.495810000000		
121.7792170000 '		
12/272 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
0759671	[/ccmpleted/new finding(s)	
	IX.	
RIANGLE POST 70/PA		V1. V. C. 11 -
·	I jnot inspetd this patrol	T MING I'N CONDUCTOR NOT SECURE-
	Notes: '02 Survey: C015308	* King YIN CONDUCTOR NOT SECURE- LOOSE TIEWIRE - EXPEDITE! VAIVS MADE - CLAMY TOP INSTAIND
8.495989000000	1 ( Can ( ) )-	TANTED TE WILL EXPEDITE
121.7790710000	- IEMA KE	VAIVS MADE - CLANT TON INSTAILE
12/273 SINGLE WOOD POLE		Total # of Attachments:
768189	[ ]completed/new finding(s)	
EL BYN ARM 1 (1/6)	[ ]pre-existing cond chked	
1-1 (NC)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015307	
3.496577000000		
121.7786160000		
12/274 SINGLE WOOD POLE	completed/no problems	Total & of Attachments.
0657542 - A		Total # of Attachments:
Z., /.~	[ ]completed/new finding(s)	
THIN AREA THICE	[]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015306	
	THE CALL OF COTTON	
3.497099000000 121.7782210000	nood. Sh daning. college	

Page 35

Inspector Name : COOPER

Date Inspected : 3-6-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	THOPECCION KESUIC	Attachment Type/Owner Listed
Framing Config		Accadement Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	notes	
Long:		
012/275 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40695552	( ]completed/new finding(s)	
	[]pre-existing cond chked	
TRIPAGLE POST 70 (H(e)	[]not inspetd this patrol	
, , , ,	Notes: '02 Survey: C015305	
38.497664000000		
-121.7777560000		
012/276 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40599472	[ ]completed/new finding(s)	
TRIANCLE POST 70	[ ]pre-existing cond chked	
7H(c)	( ] not inspetd this patrol	
·	Notes: '02 Survey: C015304	( 31 (
38.498176000000	MONITOR ROTTEN POLE	AND STUB ( STUB HAS "C" Trass
-121.7773380000		
013/277 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40677768	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	<b> </b>
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015302	
38.498624000000		
-121.7770560000		
013/278 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40592627	1   completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[ ]not inspetd this patrol	
38.499073000000	Notes: '02 Survey: C015301	
-121.7767790000		
013/279 SINGLE WOOD POLE		Total # of Attachments:
40612714	[]completed/new finding(s)	rotal & of Accaciments:
TRIANGLE POST 20 1 (NC)	[ ]pre-existing cond chked	
1-T (W)	[] not inspetd this patrol	
	Notes: '02 Survey: C015300	POLE NEEDS STUBB
38.499515000000		
-121.7765210000		
013/280 SINGLE WOOD POLE -	completed/no problems	Total # of Attachments:
40874431	[ ]completed/new finding(s)	
TRIMELE DOST ( L( c')	[ ]pre-existing cond chked	
- IIIC 3	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015299	
38.50002000000		
-121.7760980000		
013/281 SINGLE WOOD POLE		Total # of Attachments:
40875503	[ ]completed/new finding(s)	
THIANGLE POST TO HIC	[]pre-existing cond chked	
1116	[ ]not inspetd this patrol	
38 500640000000	Notes: '02 Survey: C015298	
38.500648000000		
-121.7755010000	I formation to the second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second seco	Dobal H of The land
013/282 SINGLE WOOD POLE	[ ] completed/no problems [ ] completed/new finding(s)	Total # of Attachments:
TRIANGLE POST 75/17/	[]pre-existing cond chked	
111(0)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015297	
38.501252000000		·
-121.7750190000		

Page 36

Date Inspected : 3-6

Inspector Name : Cooper

Medium Impact

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

: 41620567 PATR/INSP 60067 DIXON-VACA #2+ Order

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
013/283 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40817754	[ ]completed/new finding(s)	
TREANGLE POST 79	[ ]pre-existing cond chked	
71 FICES	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015296	
38.501781000000		
-121.7745220000		
013/284 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40767570	[ ]completed/new finding(s)	
FLAT PIN ARM ( RAMP	[ ]pre-existing cond chked	
•	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015295	
38.502385000000		
-121.7739410000		
013/285 SINGLE WOOD POLE 40768191	completed/no problems	Total # of Attachments:
40768191 TRI PIN ARM	[]completed/new finding(s)	
IKT PIN ARM	[ ]pre-existing cond chked [ ]not inspetd this patrol	
	Mores, 102 Surgery, Col 5204	
38.50300000000	Notes: 102 Survey: C015254	for, ok This cycle
-121.7734350000	HATA THE SOME P	or or in's offer
013/286 SINGLE WOOD POLE	X completed/no problems	Total # of Attachments:
40665558	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015293	
38.503595000000		
-121.7729140000		
013/287 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40677764	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015292	
38.50420300000		
-121.7723710000		
013/288 SINGLE WOOD POLE	[ ]completed/no problems	Total # of Attachments:
40599435		
TRI PIN ARM	[ ]pre-existing cond chked	110
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015291	
38.504792000000		
-121.7718820000		
013/289 SINGLE WOOD POLE		Total # of Attachments:
40601239	[ \completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[ ]not inspetd this patrol	
38.50523300000	Notes: '02 Survey: C015290	
-121.7714260000		
013/290 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40868348	[]completed/new finding(s)	TOTAL TOT ACCACHMENCA.
TRIANGLE FOST 70	[ ]pre-existing cond chked	
7 7	[] not inspetd this patrol	
	Notes: '02 Survey: C015289	
38.505609000000		

Page 37

Inspector Name : _ Date Inspected : _

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
013/291 SINGLE WOOD POLE	Completed/no problems	[m-1-1 # -6 244-41
40869010 /		Total # of Attachments: 1
TRI PIN ARM	[]completed/new finding(s)	DIST-0310456 1
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015288	
38.50623000000	12KU-No. Bloom	ara.
-121.7705550000		
013/292 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40816631	[]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015287	
38.506857000000		
-121.7700410000		
013/293 SINGLE WOOP POLE	completed/no problems	Total # of Attachments:
40825195	[ ] completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
212 221 1241 4	[] not inspetd this patrol	
	Notes: '02 Survey: C015286	
38.507455000000	MONITOR XARM	
-121.7694490000	MINISTER AFRA	
***************************************	3-1-1-07	(m-t-1)
013/294 SINGLE WOOD POLE 40759669	rempleted/no problems	Total # of Attachments:
, , , ,	[]completed/new finding(s)	
TRI PIN ARM V	[ ]pre-existing cond chked	,
	[]not inspetd this patrol	
	Notes: '02 Survey: C015285	
38.508053000000	MONITOR XARM	₩·
-121.7689340000		
013/295 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40768193	[ ]completed/new finding(s)	
TRI PIN ARM	pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[ ] not inspetd this patrol	Pole Replace - STITBAD, NEED & DO
	Notes: '02 Survey: C015284	THE VOLUME OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE PARTY OF THE
38.508642000000	MONITOR SHELL ROT P	OLE
-121.7684120000		
013/296 SINGLE WOOD POLE	Decmoleted/no problems	Total # of Attachments:
40665585	[]completed/new finding(s)	
TRI POST (- ( W/C)	[ ]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
	Notes: '02 Survey: C015283	
38.509216000000		
-121.7678830000	NEWER TO	C
013/297 SINGLE WOOD POLE		
10695639	completed/no problems	Total # of Attachments:
<i>i</i> /	[]completed/new finding(s)	
RI PIN ARM	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015282	
8.509837000000	,	
	Completed/no problems	Total # of Attachments:
13/298 SINGLE WOOD POLE		Total # OF Attachments:
13/298 SINGLE WOOD POLE		Total # Of Attachments:
121.7673300000  13/298 SINGLE WOOD POLE  10592626  AT PEN RAM  TEDIUM EQP (AERIAL LIFT; LINE TR	[ ]completed/new finding(s)	Total # Of Attachments:
13/298 SINGLE WOOD POLE 0592626 REPRESENT (UIO)	[]completed/new finding(s) []pre-existing cond chked []not inspctd this patrol	Total # Of Attachments:
13/298 SINGLE WOOD POLE 0592626 NI PIN PAM ( (VIO)	[ ]completed/new finding(s) [ ]pre-existing cond chked	Total # Of Attachments:

Page 38

Inspector Name : COOPER Date Inspected: 3-8-12

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	THEPECCION WESTER	Attachment Type/Owner Listed
Framing Config		Accountable 1750, outside 11500
Access:		i
	Notes	
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
014/299 SINGLE WOOD POLE	Teompleted/no problems	Total # of Attachments:
40869832	[ ]completed/new finding(s)	
TRI POST (P/C)	[ ]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015280	
38.511111000000		
-121.7662020000		
014/300 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40875505	Dicompleted/new finding(s)	
TRI PIN	[ ]pre-existing cond chked	110 00
	[ ]not inspetd this patrol	REFRAME TO T-1
	Notes: '02 Survey: C015279	
38.511592000000		
-121.7657800000		
014/301 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40816629	[]completed/new finding(s)	
	[ ]pre-existing cond chked	
TRI PIN AND (M/C)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015278	· · · · · · · · · · · · · · · · · · ·
38.512178000000	Rocco. De Barvey. State	
-121.7652480000		
014/302 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40825197	[ sompleted/new finding (s)	
TRI PIN ARM	[ ]pre-existing cond chked	
TRI PIN ARM	[]not inspetd this patrol	
	Notes: '02 Survey: C015277	
38.512785000000	Notes: 02 Strivey. Col32:	
-121.7646830000	completed/no problems	Total # of Attachments:
014/303 SINGLE WOOD POLE 40752056	[]completed/new finding(s)	-
FLAT PIN ARM CHANG	[]pre-existing cond chied	
FLAT PIN ARM		
	[ ]not inspctd this patrol Notes: '02 Survey: C015276	
38.513385000000	MONITOR HAIM TOD	
-121-7641790000	12KU - NO 5.	
014/304 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40768195		
TRI FOST ( (MIC)	re-existing cond chked	
( ) ( )	not inspetd this patro!	
	Notes: '02 Survey: C01527	
38.513996000000		
-121.7636200000		
014/305 SINGLE WOOD POLE	I Tcompleted/no problems	Total # of Attachments: 1
40657539	[ ]completed/new finding(s	
THE POST 70 (HC)	Depre-existing cond chked	
	[ ]not inspetd this patrol	1019 YCentree - 2010 - 2010
	Notes: '02 Survey: C015274	
38.514440000000	12KV-NO 7. B	0141-
-121.7632160000		
014/306 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40695556	[ ]completed/new finding(s	PHON-UNKNOWN 1
TRIANGLE FOST 70 THE	[ ]pre-existing cond chked	
(,,,)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015273	
38.514919000000		
-121.7627760000		
<del></del>		

Page 39

Inspector Name : Cooper Date Inspected: 3-8

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	Moces	
Long:		
014/307 SINGLE WOOD POLE		Total # of Attachments: 1
40599473	[ ] completed/new finding(s)	PHON-UNKNOWN 1
TRIANCLE FOST TO H (c)	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015272	
38.515377000000	1	
-121.7623490000		
014/308 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40601237	[]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	ENON-ON I
ELL FILLS	-	
	[] not inspetd this patrol	
	Notes: '02 Survey: C015271	
38.515661000000		
-121.7620670000		
014/309 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40868346	[ ]completed/new finding(s)	PHON-UNKNOWN 1
TETANOLE POST O PAC	[ ]pre-existing cond chked	
TVAC	[ ]not inspetd this patrol	* Dry out Burdes Auchor Ry
	Notes: '02 Survey: C015270	11 5 4 000 1 100 1 1 1 1 1 1 1 1 1 1 1 1 1 1
38.516012000000		
-121.7617260000		
014/310 SINGLE WOOD POLE		(Total # of Abbachanta 1
1007EE24 Adi. Sm.		Total # of Attachments: 1
40875534 (M. DEL TRI PIN ARM DEAD END ( NO)	[]completed/new finding(s)	PHON-UNKNOWN 1
TRI PIN ARM DEAD END	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015269	
38.516735000000		
-121.7610650000	le .	
014/311 SINGLE WOOD FOLE	completed/no problems	Total # of Attachments: 1
10823518	[ ]completed/new finding(s)	PHON-UNKNOWN 1
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015268	
88.5182860000 <b>0</b>	Judge Car Survey Consider	
121.7597080000		
14/312 SINGLE WOOD POLE	N. Zamalanad/a	Image 2 at 2 at 2 at 2 at 2 at 2 at 2 at 2 a
	completed/no problems	Total # of Attachments:
10817752	[]completed/new finding(s)	
RI PIN ARM	[ ]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C015267	
8.519092000000		
121.7590050000	16	
14/313 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0759912	[ ]completed/new finding(s)	
RIANGLE POST 70	[ ]pre-existing cond chked	
164	[] not inspetd this patrol	
-	Notes: '02 Survey: C015266	
8.519711000000	Durvey: Col5266	
121.7584950000		
	1	
14,314 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0665561	[ ]completed/new finding(s)	
RIANGLE POST 70	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015265	
8.520180000000		

Inspector Name : _ Date Inspected : _

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
	Water	
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
014/315 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40695560	[ ]completed/new finding(s)	
TRIANGLE POST 70 (H(c)	[ ]pre-existing cond chked	
26 00/	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015264	
38.520698000000	MONITOR OLD POLE SH	ELL ROT
-121.7576500000		
014/316 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40592624	completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015263	
38 50100400000	Acces: 102 Survey: C015263	
38.521094000000		
-121.7573030000		
015/317 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40602835 MAT DIN ARM (-1 (NC)	[ ]completed/new finding(s)	
MAT PIN ARM \- L (M)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015262	
38.521668000000		
-121.7568280000		
015/318 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
	Trompleted/new finding(s)	
TRIANGLE FOST 70 (KI P.)	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	1 177 - 7 A
	Notes: '02 Survey: C015261	Colinated Cal
38.522396000000	Notes. 02 Survey. CV23202	
-121.7561700000		
015/319 SINGLE WOOD POLE	100-100-100-100-100-100-100-100-100-100	(man - 1 m - 6 man - 1 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m - 6 m
	completed/no problems	Total # of Attachments:
40875540	[]completed/new finding(s)	
TRI DIN ODY	[ ]pre-existing cond chked	
<b>~</b> /	[ ] not inspetd this patrol	
	Notes: '02 Survey: C015260	
38.522974000000		
-121.7556600000		
015/320 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40823520 T-1(N/C)	[ ]completed/new finding(s)	
3 HORIFONTAL POST DELTA	[ ]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015259	
38.523563000000		
-121.7551340000		
015/321 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
	[]completed/new finding(s)	
40817750		
FRIANGLE POST 70 TPA(C)	[]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015258	
38.524156000000	1.4:	
-121.7545950000	MINOR ARM ROT	
015/322 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40759665	[]completed/new finding(s)	
TRI PIN ARM	Thre-existing cond chked	(FI) U. L. F
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015257	
38.524753000000		
-121.7540560000		

Page 41

Inspector Name : COOPER Date Inspected : _

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Imprection Readic	Attachment Type/Owner Listed
Framing Config		vergemment tabelowner praced
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	į	
Long:		
015/323 SINGLE WOOD POLE	X completed/no problems	Total # of Attachments:
40768197	[]completed/new finding(s)	
TRIMIGER DOST 70 TPA (c)	[]pre-existing cond chked	l l
1		i i
	[]not inspctd this patrol	
	Notes: '02 Survey: C015256	
38.52531500000 <b>0</b>		
-121.7535300000		
015/324 SINGLE WOOD POLE	[ ]completed/no problems	Total # of Attachments:
40665584	[ ]completed/new finding(s)	
(REP, OC)	pre-existing cond chked	
1	[ ]not inspetd this patrol	* Tr. Pin REFrame
,	Notes: '02 Survey: C015255	
38.525919000000		
.121.7530040000		·
015/325 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40677760	[]completed/new finding(s)	
	_	
FIELD SWITCH STRUCTURE	[]pre-existing cond chked	i
TVA	[]not inspetd this patrol	
	Notes: '02 Survey: C015254	
38.526503000000	* Am HAR W.	NOR ROT 39 KEY INSUL'S, NO HV
-121.7524860000	1 . 143.2 [(-12) ]((-	Note 1001, saken mones, no Hr
015/326 SINGLE WOOD POLE	[ ]completed/no problems	Total # of Attachments:
40759667	completed/new finding(s)	
DVDE	[ ]pre-existing cond chked	(2)
	[ ] not inspetd this patrol	
(n/c)	Notes: '02 Survey: C015253	XVINIO 25/1/52 TH DIGITA
38.527098000000	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
-121.7519420000	1	
015/327 SINGLE WOOD POLE SW 77	[]completed/no problems	Tropal # -6 Accessor
40677689		Total # of Attachments:
	completed/new finding(s)	l
DVDE	[ ]pre-existing cond chked	(4)
•	[ ]not inspctd this patrol	* (1) AUTOSPICE IND-GOY
(h/c)	Notes:	
38.52715200 <b>0</b> 000		
-121.7520010000		
015/328 SINGLE WOOD POLE		Total # of Attachments:
40665535	[]completed/new finding(s)	
TRIANGLE POST 70 TH(4)	[ ]pre-existing cond chked	l i
	[] not inspetd this patrol	
	Notes:	
38.526538000000		
-121.7525540000	12KU-NO BBOND	
015/329 SINGLE WOOD POLE		Im1 H - C x 1   C x
	completed/no problems	Total # of Attachments:
40751991 TRI FIN ALM T- ( (MC)	[ ]completed/new finding(s)	
THE FIN ALLON ! - ( COTY )	[ ]pre-existing cond chked	
( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )	[ ]not inspetd this patrol	
	Notes:	
38.525977000000		
-121.7530460000	12KU - NO B DOUD	
015/330 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40752052	[ ]completed/new finding(s)	
(c)	[ ]pre-existing cond chked	
1 173 65	[ ] not inspctd this patrol	
	Notes:	
38.525378000000		
	1	
-121.7535600000		

Page 42

Inspector Name: COOPER

Date Inspected: 3-9-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
015/331 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40817718	[]completed/new finding(s	
TH(c)	[ ]pre-existing cond chked	
11(0)	[] not inspetd this patrol	
•	Notes:	
38.524775000 <b>0</b> 00	Notes:	
-121.7541140000	12KU-NO B. DOND	· Pole HAS C' Truss
		· loie Ling C ivasz
015/332 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
10823496	[]completed/new finding(s	
ri pin arm <del>tramp (</del> C)	[ ]pre-existing cond chked	
-	[ ]not inspetd this patrol	
	Notes:	•
38.524198000000	In VI No P to	
121.7546470000	12 KV-NO B. BOND	
115/333 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40868978 Z LLON C	[]completed/new finding(s	
EST PAHPO ()	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes:	
8.523621000000		
121.7551890000	12KU NO B. 120m	
15/334 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0874413	Licompleted/new finding(s)	1 1019 125T N/S - LINIA. 1 ADOUR 50"
TPA (c)	Libre-existing cond chked	10 to V 11 julious trivia
[3] A.G.	[ ]not inspetd this patrol	Ralman To be To San Branch
•	Notae:	Relocate Pole - Elden Bong  Relocate Pole - Elden Bong  Relocate Pole - Elden Bong  Restruction plans - NotiFied J. MSSELL  Total # of Attachments:
8.523002000000	WANGWA LYNG	KO FULL TUEES UND TO CINC
121,7557110000	uc Davis a	MASTELLATER Plant NET'C' - T MASSELL
		Total # of attachments:
15/335 SINGLE WOOD POLE	//completed/no problems	
0601204	( ) comprehenties introducted (a)	,
0601204	[ ]pre-existing cond chked	
115/335 SINGLE WOOD POLE 0601204 RIANGLE POST 70 (HC)	[ ]pre-existing cond chked [ ]not inspetd this patrol	
0601204 RTANGLE POST 70 (HC)	[ ]pre-existing cond chked	
0601204 RIANGLE POST 70 (HC) 8.522417000000	[ ]pre-existing cond chked [ ]not inspetd this patrol	
0601204 RIANGLE POST 70 ((C) 8.522417000000 121.7562270000	[] pre-existing cond chked [] not inspetd this patrol Notes:	
8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE	[]pre-existing cond chked []not inspetd this patrol Notes:	Total # of Attachments:
8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE	[]pre-existing cond chked []not inspetd this patrol Notes:  []completed/no problems []completed/new finding(s)	Total # of Attachments:
0601204 RIANGLE POST 70 (HC) 8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414	[] pre-existing cond chked [] not inspetd this patrol Notes: [] completed/no problems [] completed/new finding(s) [] completed/new finding(s)	Total # of Attachments:
8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE	[]pre-existing cond chked []not inspetd this patrol Notes:  []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspetd this patrol	Total # of Attachments:
0601204 RHANGLE POST 70 (HC) 8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM	[] pre-existing cond chked [] not inspetd this patrol Notes: [] completed/no problems [] completed/new finding(s) [] completed/new finding(s)	Total # of Attachments:
0601204 RHANGLE POST 70 (HC) 8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM	[]pre-existing cond chked []not inspetd this patrol Notes:  []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspetd this patrol	Total # of Attachments:
0601204 RHANGLE POST 70 (HC) 8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM	[] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/no problems [] completed/new finding(s) [] byre-existing cond chked [] not inspetd this patrol Notes:	Total # of Attachments:
0601204 RFANGLE POST 70 (HC) 8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM 8.521790000000 121.7568280000 16/337 SINGLE WOOD POLE	[] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes:	Total # of Attachments:  XAM Koulib such,  Total # of Attachments:
0601204 RTANGLE POST 70 (HC) B.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM B.521790000000 121.7568280000 121.7568280000 16/337 SINGLE WOOD POLE	[] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/new finding(s)	Total # of Attachments:  XAM Koulib such,  Total # of Attachments:
0601204 077NIGLE POST 70 (HC) 08.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM 08.521790000000 121.7568280000 16/337 SINGLE WOOD POLE 1599412	[] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/new finding(s) [] completed/new finding(s) [] lpre-existing cond chked	Total # of Attachments:  XAM Koulib such.  Total # of Attachments:
0601204 RTANGLE POST 70 (HC) B.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM B.521790000000 121.7568280000 121.7568280000 16/337 SINGLE WOOD POLE	[] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/new finding(s)	Total # of Attachments:  XAM Koulib such.  Total # of Attachments:
0601204 RHANGLE POST 70 (HC)  8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM  8.521790000000 121.7568280000 16/337 SINGLE WOOD POLE 0599412	[] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/new finding(s) [] completed/new finding(s) [] lpre-existing cond chked	Total # of Attachments:  XAM Koulib such,  Total # of Attachments:
0601204 RTANGLE POST 70 (HC)  8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM  8.521790000000 121.7568280000 126/337 SINGLE WOOD POLE 0599412 RI PIN ARM	[] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/new finding(s) [] completed/new finding(s) [] lpre-existing cond chked [] not inspetd this patrol	Total # of Attachments:  XAM Koulib such,  Total # of Attachments:
0601204 RTANGLE POST 70 (HC)  8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM  8.521790000000 121.7568280000 126/337 SINGLE WOOD POLE 0599412 RI PIN ARM	[] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes:  [] completed/new finding(s) [] completed/new finding(s) [] lpre-existing cond chked [] not inspetd this patrol	Total # of Attachments:  XAM Koulib such,  Total # of Attachments:
8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE	[]completed/no problems []completed/no problems []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes:  []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes:	Total # of Attachments:  XAM Koulib such,  Total # of Attachments:
0601204 RTANGLE POST 70 (HC)  8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM  8.521790000000 121.7568280000 16/337 SINGLE WOOD POLE 1599412 RI PIN ARM  8.521131000000 121.7574090000	[]completed/no problems []completed/no problems []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes:  []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes:	Total # of Attachments:  XAM Kollib such.  Total # of Attachments:
8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM  8.521790000000 121.7568280000 121.7568280000 121.7568280000 121.7574090000 121.7574090000 121.7574090000 121.7574090000	[]completed/no problems []completed/no problems []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes:  []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes:  []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes:	Total # of Attachments:  XAM Kollib such.  Total # of Attachments:
0601204 077NGLE POST 70 ( ) 08.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM 08.521790000000 121.7568280000 126/337 SINGLE WOOD POLE 0599412 RI PIN ARM 08.521131000000 121.7574090000 121.7574090000 121.7574090000 121.7574090000	[]completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []not inspctd this patrol Notes:  []completed/no problems []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes:  []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems	Total # of Attachments:  XAM Kollib such.  Total # of Attachments:
0601204 077NGLE POST 70 ( ) 08.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM 08.521790000000 121.7568280000 126/337 SINGLE WOOD POLE 0599412 RI PIN ARM 08.521131000000 121.7574090000 121.7574090000 121.7574090000 121.7574090000	[ ]pre-existing cond chked [ ]not inspetd this patrol Notes:  [ ]completed/no problems [ ]completed/new finding(s) [ ]pre-existing cond chked [ ]not inspetd this patrol Notes:  [ ]completed/new finding(s) [ ]pre-existing cond chked [ ]not inspetd this patrol Notes:  [ ]completed/new finding(s) [ ]pre-existing cond chked [ ]not inspetd this patrol Notes:  [ ]completed/new finding(s) [ ]pre-existing cond chked [ ] loop leted/new finding(s) [ ] pre-existing cond chked [ ] not inspetd this patrol	Total # of Attachments:  XAM Kollib such.  Total # of Attachments:
0601204 077NGLE POST 70 (HC)  8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM  8.521790000000 121.7568280000 16/337 SINGLE WOOD POLE 0599412 RI PIN ARM  8.521131000000 121.7574090000 16/338 SINGLE WOOD POLE 1695497 RI PIN ARM	[]completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []not inspctd this patrol Notes:  []completed/no problems []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes:  []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems	Total # of Attachments:  XAM Kollib such.  Total # of Attachments:
0601204 RTANGLE POST 70 (HC)  8.522417000000 121.7562270000 15/336 SINGLE WOOD POLE 0599414 LAT PIN ARM  8.521790000000 121.7568280000 16/337 SINGLE WOOD POLE 1599412 RI PIN ARM  8.521131000000 121.7574090000 16/338 SINGLE WOOD POLE	[ ]pre-existing cond chked [ ]not inspetd this patrol Notes:  [ ]completed/no problems [ ]completed/new finding(s) [ ]pre-existing cond chked [ ]not inspetd this patrol Notes:  [ ]completed/new finding(s) [ ]pre-existing cond chked [ ]not inspetd this patrol Notes:  [ ]completed/new finding(s) [ ]pre-existing cond chked [ ]not inspetd this patrol Notes:  [ ]completed/new finding(s) [ ]pre-existing cond chked [ ] loop leted/new finding(s) [ ] pre-existing cond chked [ ] not inspetd this patrol	Total # of Attachments:  XAM Kollib such.  Total # of Attachments:

Page 43

Funct Loc: ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Date Inspected : 3-8-

Inspector Name : COOPEN

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
	Inspection Result	
Equip #		Attachment Type/Owner Listed
Framing Config		·
Access:		
	37-1	
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		1
016/339 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40665533	[]completed/new finding(s)	
*		
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes:	
38.520216000000		
-121.7582000000		
016/340 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40759871	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes:	
38.519782000000		
-121.7585640000	4	
016/341 SINGLE WOOD POLE	[   Completed/no problems	Total # of Attschments:
40767530	[]completed/new finding(s)	1 · · · · · · · · · · · · · · · · · · ·
TRIANGLE POST 70	[ ]pre-existing cond chked	
	[]not inspctd this patrol	}
	Notes:	
38.519464000000		
-121.7588470000		
016/342 SINGLE WOOD POLE	[ ]completed/no problems	Total # of Attachments:
40825169	completed/new finding(s)	
TRIANGLE POST 70	Dre-existing cond chked	
•	[ ]not inspctd this patrol	Pole Replace ( Inhouse Cornel) zyr
		100000
	Notes:	Decker lastes and some
38.519152000000		The works we from come
-121.7591560000		
016/343 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40816590	[]completed/new finding(s)	
**************************************	1	ļ
TRI PARM THE (NIC)	[ ]pre-existing cond chked	<u> </u>
	[ ]not inspetd this patrol	
	Notes:	
38.518317000000		
-121.7598900000		
	N. 32	
016/344 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40868980	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
TRI PIN ARM TH(c)	[]not inspctd this patrol	
14.6		
	Notes:	
38.516828000000		
-121.7611830000		
016/345 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40868308	[] completed/new finding(s)	
TRIANCLE POST 78 (H(C)	[ ]pre-existing cond chked	
( 51(-)	[ ]not inspetd this patrol	
•	Notes:	
38.516023000000		
-121.7619200000		
	W.C. and J. t. al.	
016/346 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40604074	[]completed/new finding(s)	
TRIANGLE FOST 70 / 10 A	[ ]pre-existing cond chked	
( 17)	[ ]not inspetd this patrol	
• •	Notes:	
30 51530300000	10000	i
38.515707000000		
-121.7622080000		

Page 44

Inspector Name : COOPER 

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Transaction Desirate	
	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	<u> </u>
Lat:		
Long:		
016/347 SINGLE WOOD POLE		Total # of Attachments:
40592590 / / ~	[ ]completed/new finding(s)	
TRIMISEE POST 77 W(C)	[]pre-existing cond chked	
1 // 0.0	[] not inspetd this patrol	
	Notes:	
38.515464000000		
-121.7624650000		
016/348 SINGLE WOOD POLE	Lompleted/no problems	Total # of Attachments:
40677694	[]completed/new finding(s)	
TREMOLE POST 70	I hre-evicting good shied	
4-1140	[ ]pre-existing cond chked [ ]not inspetd this patrol	
\ \ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	[ ] not inspetd this patrol	
	Notes:	
38.514934000000		
-121.7628890000		
016/349 SINGLE WOOD POLE		Total # of Attachments:
1		
TRIANGLE FOST 70 (C)	[]completed/new finding(s)	
14/0	[ ]pre-existing cond chked	
1,1,(0)	[ ]not inspetd this patrol	
/	Notes:	
38.514488000000		
-121.7632630000		
016/350 SINGLE WOOD POLE		Tabal 4 of Salaria
40759873		Total # of Attachments:
	[ ]completed/new finding(s)	
TIMENT POST TO TILL (NE)	[ ]pre-existing cond chked	
1 (010)	[ ]not inspctd this patrol	
	Notes:	
38.514026000000	l	<
-121.7637050000	has and por	in Alderos.
016/351 SINGLE WOOD POLE		Total # of Attachments:
40767522	Tompleted/new finding(s)	
FLAT PIN ARM TUAMP	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	*BROKED BOND WIRE. TOP ANN, NORTH PLASE
	Notes	TO DECENT CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CONTRACTOR OF THE CO
38.513416000000	Mocca.	Top Arm Harty Dass
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
-121.7642340000		·
016/352 SINGLE WOOD POLE		Total # of Attachments:
40825175	(s)	
TRI PIN	[ ]pre-existing cond chked	N 55
	[ ]not inspetd this patrol	Re-Frans T-1
50 F155500000	Notes:	
38.512820000000	KKU- No \$.	Bris
-121.7647610000		
016/353 STNSLE WOOD DOLE	bacompleted/no problems	Total # of Attachments:
40823494 T3P	[ ]completed/new finding(s)	
	[]pre-existing cond chked	
一丁一(少に)	_	
	[ ]not inspetd this patrol ]	
	Notes: MONITOR XARM	
38.512221000000		
-121.7653210000		
016/354 SINCLE WOOD POLE	pleted/no problems	Total # of Attachments:
10875483 TSP	[]completed/new finding(s)	" or recomments;
MINICE FOR TOT - ( NA)		
	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes:	
38.511607000000		
121.7658760000		

Inspector Name : Cooper Date Inspected : 3-8-12

Funct Loc: ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Indpection Reserve	Attachment Type/Owner Listed
Framing Config		Mecacumient Type/Owner Histed
Access:		
HOST Tech ID/Equip #:	Notes	1
Lat:		
Long:		
016/355 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40874417	[]completed/new finding(s)	
THE PIN ARM THE	[ ]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes:	
38.511153000000		
-121.76626 <b>7</b> 00 <b>00</b>		
017/356 SINGLE WOOD POLE		Total # of Attachments:
40592592	[ ]completed/new finding(s)	
TRE-PEN ARM T	[ ]pre-existing cond chked	
T-I (uk)	[ ]not inspetd this patrol	
/	Notes:	
38.510432000000		
-121.7668960000		
017/357 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40695501	[ ]completed/new finding(s)	
TRI	[ ]pre-existing cond chked	
Tra 175	[ ]not inspetd this patrol	
1 12	Notes:	
38.509856000000		
-121.7674070000		
017/358 SINGLE WOOD POLE	cmpleted/no problems	Total # of Attachments:
40657505	[ ]completed/new finding(s)	
TRI DIWART (H(0)	[ ]pre-existing cond chked	
1,41	[ ]not inspetd this patrol	
	Notes: Pale Has VEDT	cle Piece of Pole Jode.
38.509290000000		
-121.7679590000	12 UV-Vo B. Bou	IN .
017/359 SINGLE WOOD POLE	[ ]completed/no problems	Total # of Attachments:
40768165	[ ]completed/new finding(s)	
TRI PIN ARM	pre-existing cond chked	$ \alpha, \alpha $
	[ ]not inspetd this patrol	Pok Rydges
	Notes:	
38.508675000000	12KU-NO 3. Bo	51/6
-121.7684710 <b>00</b> 0	1 1200-101 200	
017/360 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40759619	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: POLE LEANING - 8/14,	/2001
38.508100000000	WONLITOR XARM	
-121.7690050000	12KV-NO B.B	pan y
017/361 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40825173	[ ]completed/new finding(s)	
40825173 TRI PEN ARM ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( (	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes:	
38.507489000000	Neweritole	
-121.7695310000		
017/362 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40816592	[]completed/new finding(s)	
TRI PIN ARM 🗸	[]pre-existing cond chked	
	[] not inspetd this patrol	
38.506882000000	Notes: MONITOR KARM	
-121.7700960000	12KV-NO 3-BOND	

Page 46

Inspector Name : _

Date Inspected : _

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

: 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		Troddemical Type/ Owner hister
Access:		i i
HOST Tech ID/Equip #:	Notes	
Lat:	11000	
Long:		
017/363 SINGLE WOOD POLE	31.11	
•	completed/no problems	Total # of Attachments:
40875475	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	* Duy out Anchor Ros NEW goy Marke
	[ ]not inspctd this patrol	To Day out Anchor Ross NEW aux Marks
	Notes:	100
38.506258000000		
-121.7706100000		
017/364 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40868310	[ ]completed/new finding(s)	
TRIANGLE POST 70	[ ]pre-existing cond chked	]
TRIANGLE POST 70 (N)	[ ]not inspetd this patrol	i i
	Notes:	
38.505652000000		
-121.7711700000		
017/365 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40612607	[] completed/new finding(s)	
TRI PIN ARM		
area a the Mont -	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
75 F0747400000	Notes:	
38.505131000000	MINOR XAM	
-121.7716400000		
017/366 SINGLE WOOD POLE	1 completed/no problems	Total # of Attachments:
40592594	[ ]completed/new finding(s)	
IRI PIN ARM	[ ]pre-existing cond chked	<b> </b>
	[ ]not inspetd this patrol	
	Notes:	
38.504517000000	sa.f	
-121.7721690000	124 No 3. Bus.	
017/367 SINGLE WOOD POLE		Total # of Attachments:
40695477	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes:	
38.503914000000		
-121.7726750000	TRU-NO B. BOND	
017/368 SINGLE WOOD POLE	Completed/no problems	matel H of the land
10665539		Total # of Attachments:
TRI PIN ARM	[] completed/new finding(s)	
AL PIN AKM	[]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes:	
8.503328000000	111.64 2-	
121.7732180000	No lake B.B.	ug .
17/369 SINGLE WOOD POLE	//completed/no problems	Total # of Attachments:
0759875	[ ] completed/new finding(s)	
RI DIN ARM ( C )	[ ]pre-existing cond chked	
411.	[ ]not inspetd this patrol	
	Notes:	
8.50274000000		
121.7737530000	Ko 12KU B.Bo.	u ()
17/370 SINGLE WOOD POLE		Total # of Attachments:
0759621	[]completed/new finding(s)	" 21 Metatementes.
TAT PIN ARM	[]pre-existing cond chked	
LAT PIN ARM RAMP		
•	[]not inspetd this patrol	
2 50225600000	Notes:	
8.502156000000 121.7743030000	NO KINU B.B	3 (1 )
		5 - ( ) ()

Page 47

Inspector Name : Cooper Date Inspected : 3-6-

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Description of Mark Th		
Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		** ,
Access:	1	
	37 . L	
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
017/371 SINGLE WOOD POLE	Acompleted/no problems	Total # of Attachments;
40825171	Tompieted/no problems	
	[ \completed/new finding(s)	İ
TRIANCLE POST 70	[ ]pre-existing cond chked	
THE C)	[ ]not inspetd this patrol	
1 7 (50)	Notes:	
38.501564000000	A0003,	
	10101-12	3
-121.7748120000	12 KU- HOB	- 780D
017/372 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40816594	[ ]completed/new finding(s)	
TRIANCLE DOGT TO	[ ]pre-existing cond chked	
71H(U		
"()	[ ]not inspetd this patrol	
	Notes:	
38.500972000000	101/	
-121.7753460000	12 KV-NO R3	Solate
017/373 SINGLE WOOD POLE		Total # of Attachments:
40875477	[ ]completed/new finding(s)	
TRIANGLE FOST 70	[ ]pre-existing cond chked	
$\neg T \mathcal{P}_{\Lambda}$	[ ]not inspetd this patrol	
1 173	Notes:	
38.500540000000	13 KU-100 B. BOW	
-121.7757700000		$\rho$
Q17/374 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40868312	[]completed/new finding(s)	i a managementa.
TRIANCLE POST 78	-	1
100	[ ]pre-existing cond chked	!
TPA	[ ]not inspctd this patrol	
	Notes:	
38.499994000000		
-121.7762200000	12 KU-NO B. BON	
	h /	
017/375 SINGLE WOOD POLE		Total # of Attachments:
40612604	[ ] completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes:	
38.4995 <b>77</b> 0000 <b>00</b>	12 KU - NO B. D	NUN
-121.7765790000	10 100 - 1 1	o. 2
017/376 SINGLE WOOD POLE		Total # of Attachments:
40599420		Total 4 of Accaements:
	[ ]sompleted/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	41
	[ ]not inspetd this patrol	* Installed Vis Strips
	Notes:	1.5 511 1
38.499122000000	5/0000 11	AS MILLOR ROT
	XAIM TH	AS INVIDAGE ADT
-121.7768650000		
017/377 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40677698	[ ]completed/new finding(s)	
TOT DIN ARM	[ ]pre-existing cond chked	,
H(U)	_	
	[ ]not inspetd this patrol	
	Notes:	
38.498650000000	1261 . 500	
-121.7771600000	12KU-NO B.BO	<i>VO</i>
019/378 SINGLE WOOD POLE		
		Total # of Attachments:
40599418	[ ]completed/new finding(s)	i i
TRIANGLE POST 18 11 C	[ ]pre-existing cond chked	
1111	[ ]not inspetd this patrol	
	Notes:	
38.498228000000		1
	12KU-NO B. BON	DD
-121.7774210000	1010 0100	

Page 48

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Inspector Name : Cooper Date Inspected : 3-5-12

In		
Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	_	
018/379 SINGLE WOOD POLE		Total # of Attachments:
40681688	[] completed/new finding(s)	
TPHANCE FOOT OF H (0)	[]pre-existing cond chked	
XH(°)	[]not inspetd this patrol	
1	Notes:	
38.497708000000	Notes:	
-121.7778240000		
	1.	
018/380 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40657507	[ ]completed/new finding(s)	
TRIANGLE POST 70 TOA	[ ]pre-existing cond chked	
1 , , , ,	[ ]not inspetd this patrol	
	Notes: MONITOR WOOD BRACES	
38.497129000 <b>0</b> 00	101 1111	
-121.7782790000	- Pole HAS "C"	Trusq
018/381 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40768164	[]completed/new finding(s)	
TRIANGLE POST 70 T 1	[ ]pre-existing cond chked	
1-1-(4/6)	[ ]not inspetd this patrol	
	Notes:	
38.496628000000	1.0000	
-121.7786650000		
018/382 SINGLE WOOD POLE		Total # of Attachments:
		· ·
40759623	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
14(e)	[ ]not inspctd this patrol	
	Notes:	
38.495989000000		
-121.7791200000		
018/383 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40825167	[]completed/new finding(s)	
TRIANGLE POST 70 (1)(6)	[]pre-existing cond chked	
THE POST TO THE	[] not inspetd this patrol	
1,	Notes:	
38.495 <b>7</b> 8300000	noces:	
-121.7793320000		
018/384 SINGLE WOOD POLE	completed/no problems	Total # or Attachments:
40816597	[]completed/new finding(s)	
TRIANGLE FOOT TO	[ ]pre-existing cond chked	
188-	[ ]not inspctd this patrol	
38.495615000000 Double Arms	Notes:	
38.495615000000 Double 13	1 4 5 1	V
-121.7795090000	* Some Hen	ret
018/385 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40868982	completed/new finding(s)	
TRIANGLE POST 70 TVA (0)	I lowe awighting good ableed	10 2 5
11467	[ Inot inspetd this patrol	* Broken DOND Wine - EAST Phase
	Notes:	CHONEL LOUD OCTUBE - CHOIC 1 MISS
38.495196000000		
	12KV-NOB. BON	
-121.7799430000	1. /	
018/386 SINGLE WOOD POLE	Acompleted/no problems	Total # of Attachments:
40874409	[ ]completed/new finding(s)	
THE PEN ADM (- ((N/C)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	* Chau up our pole Debais
	Notes:	
38.494645000000	., :	
-121.7805710000	NEWER POLE	

Page 49

Inspector Name : COOPER

Date Inspected : 3-5-11

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Dogg of most TD	IT an achier December	13th abroad a #
Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
018/387 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40612613	completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	X 200km, 2001) 15 5 5 5
	[ ]not inspetd this patrol	X BROKEN BOND WIKE - EAST PHASE
	Notes:	· · · · · · · · · · · · · · · · · · ·
38.494105000000		
-121.7811620000	1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1	Paral H of Shart-oaks
018/388 SINGLE WOOD POLE	[]completed/no problems []completed/new finding(s)	Total # of Attachments:
40599408 TRIANGER FOST 70 // A	[ ]pre-existing cond chked	
1 PA	[ ]not inspetd this patrol	
• •	Notes:	
38.493553000000		
-121.7817880000	12KU-NO B. BOUD	
018/389 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40677702	[]completed/new finding(s)	
TRI PIN ARM		
ARE SAN BRUS	[ ]not inspetd this patrol	+ INSTAILED GOY MARKER
	Notes:	No House
38.492990000000	Noces	
-121.7823960000	16/4 15 0-40 -	- Will DEED In he Replaces
018/390 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40665514	[]completed/new finding(s)	
TRIANGLE POST 70	pre-existing cond chked	
2022 10	[]not inspetd this patrol	
	Notes:	1 C WEE 1
38.492636000000	1,0220	·
-121.7827610000		
018/391 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40759877	[]completed/new finding(s)	
TRI PIN ARM	Spre-existing cond chked	
	[ ]not inspetd this patrol	*GEANIUS POLL-NO CHANGE
	Notes:	1/2-114
38.492113000000		
-121.7832240000	12 KU - NO 33 BOUD	
018/392 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40767518	[]completed/new finding(s)	"
TRI PIN ARM TRAMP	Title Table 1 and 1	
	[ ]not inspctd this patrol	LGAN, My Pole-Complete tole Has C
	Notes: DISTRIBUTION PT 6 S	QUATER,
38.491542000000	10 611 2 2	LEANING POLE-CONVERT POLE HOS C' Thuss Installed
-121.7837560000	1540 - NO D. DOOP	Troschied
018/393 SINGLE WOOD POLE		Total # of Attachments:
40825159	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes:	0
38.490887000000		MINOR BOT
-121.7843070000	12 Ku - No B. Dout	
018/394 SINGLE WOOD POLE		
40823490	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes:	
38.490288000000		
-121.7848410000		

Page 50

Inspector Name : Cooper

Date Inspected : 3.5

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		,
Access:	1	
HOST Tech ID/Equip #:	Notes	<u> </u>
Lat:		
Long:		
018/395 SINGLE WOOD POLE		Total # of Attachments:
40875469	[ ]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
TYAC	[ ]not inspetd this patrol	
	Notes:	
38.48970200 <b>00</b> 00	1014	
-121.7853590000	12KU-No B Bour	<u></u>
018/396 SINGLE WOOD POLE	/completed/no problems	Total # of Attachments:
40874403	[ ]completed/new finding(s)	
TRIANGLE POST 28	[ ]pre-existing cond chked	
1 PA	[ ]not inspctd this patrol	
	Notes:	
38.489134000000	12 1/11 110 # 8.	
-121.7858590000	12 KU_NO B. BOND	
018/397 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40601207	[ ]completed/new finding(s)	
TREE BIN ARM (-1 (MC)	[]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes:	
38.488633000000		
-121.7862980000	1	
018/398 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
41121534	[] completed/new finding(s)	
1 HILLS	[]pre-existing cond chked	
	[]not inspetd this patrol	
38.48805600000	Notes:	
-121.7868190000	12 KU - NO B. DOUR	
018/399 SINGLE WOOD POLE	V completed/no problems	Total # of Attachments:
405 <b>9941</b> 1	[]completed/new finding(s)	
FDI DEN AND AND AND AND AND AND AND AND AND AN	[ ]pre-existing cond chked	
THE	[ ]not inspetd this patrol	
	Notes:	
38.487548000000		
-121.78729600 <b>0</b>		
019/400 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
10677706	[]completed/new finding(s)	
TANGLE 1051 10 (NC)	[]pre-existing cond chked	
12161	[ ] not inspetd this patrol	
	Notes:	
38.487176000000		
121.7876050000		
019/401 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0599403	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes:	
8.486829000000	12 [N - NA 215] DA	7
121.7879250000	12KV - NO BRIDGE	
019/402 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
10642982	completed/new finding(s)	
PRIANGLE POST TO TYPE	[ ]pre-existing cond chked	V
•	[ ]not inspetd this patrol	* INSTALLED NEW Guy Marken
	Notes:	
88.486243000000		
-121.7884000000		

Inspector Name : Cooper Date Inspected : 3-4-12

Medium Impact

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
		TOO COMMENT TABLE TABLES
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
long:		
19/403 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
10650170	[ ]completed/new finding(s)	
TRI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes:	
88.485669000000		
	12 KU - NO B. BOW	
121.7889210000		
19/404 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0759879	[ ]completed/new finding(s)	
THE CENT ADM (H(C)	[]pre-existing cond chked	
••••	[ ]not inspetd this patrol	
	Notes:	
	Moces:	
88.485096000000	12 KU - NOBBOND	
121.7894410000		
19/405 SINGLE WOOD POLE	( completed/no problems	Total # of Attachments:
0759625	[]completed/new finding(s)	
1- (N/C)	[]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes:	
8.484464000000	NEW POLE	
121.7900000000	, , ,	
19/406 SINGLE WOOD POLE		Total # of Attachments:
0825157	[]completed/new finding(s)	
RI PIN ARM	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes:	
8.483903000000		
121.7904860000	13 KV - No B. Band	
19/407 SINGLE WOOD POLE	Manualated (na manhiama	Total # of Attachments:
•	Completed/no problems	
.0816599	[ ]completed/new finding(s)	
RI PIN ARM	[ ]pre-existing cond chked	{
	[ ]not inspetd this patrol	i i
	Notes:	
8.483376000000		
	77	
121.7910710000	12KU-NO D. DOND	
19/408 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
0875467	[ ]completed/new finding(s)	
RE PIN ARM TH(e)	[ pre-existing cond chked	
1 11 6	(Inot inspetd this patrol	Marilia Oil NOCH
	Notes:	ELEANING PILE NO CHANGE
	700003:	
8.482711000000	12 KV - NO B. BOND	
121.7916670000		
19/409 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
0874405	[]completed/new finding(s)	
RIANGLE POST 70	pre-existing cond chked	k
	[ ] not incostd this natural	Voga ville Delor - 11 al
	f luot inspect this battor	LEANING POLE - NO CHANGE
	Notes: DIST SQUATER WEST P	H
3.482097000000		h.
121.7921530000	12 KV BELOGE BONDE	
19/410 SINGLE WOOD POLE	lcompleted/no problems	Total # of Attachments:
-	1 1 Compressed/No propress	L Dansey XAM BOART Million Arm Port
0612598	completed/new finding(s)	Total # of Attachments:  * ROTTEN XAVM BEACE, M. NOR ATM ROT. G-MON TO FY
RI <b>PIN ARM</b>	Apre-existing cond chked	17 cm
	[ ]not inspctd this patrol	LEANENS POL - NO CHANGE
	Notes: DIST SQUATER WEST P	ii
		1
8.481535000000	1911	
8.481535000000 l21.7926510000	12KU NOB-BOND	

Page 52

Inspector Name : Cooper Date Inspected : 3-4

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

: 41620567

PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Inspection Result	
		Attachment Type/Owner Listed
Framing Config		
Access:	N-h-	
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
019/411 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40599405	[]completed/new finding(s)	
TRINNOLE DOST 70	ore-existing cond chked	4/
(PAC)	[ ]not inspctd this patrol	# EANING POLE - NO CHANGE
, , ,		
38.480894000000	* XARM HA	M. ()
-121.7932220000	* MARM HA	
019/412 SINGLE WOOD POLE	[ ]completed/no problems	Total # of Attachments:
40677711	[]completed/new finding(s)	
TRI PIN ADM TRAMP	pre-existing cond chked	We constitute the second
34PD(c)	[ ]hot inspctd this patrol	*LEANING BIE - No Change
<u> </u>	Notes:	
38.48032900000		
-121.7937190000		./
019/413 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40665518	[ ]completed/new finding(s)	
FRE FIR ARM (_\C)	[ pre-existing cond chked	
. —	[ ]not inspetd this patrol	* LEANING POLE-NO CHAUSE
	Notes:	
39.47974800000		
-121.7942460000		
019/414 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40761767	[ ]completed/new finding(s)	
TRI SEN ARM (C)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes:	
38.479146000000	1	
-121.7947560000		
019/415 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40767516	[ ]completed/new finding(s)	
CRESTRARM T-16	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
38 4808*****	Notes:	
38.478531000000		
-121.7953120000		
019/416 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40817720	[]completed/new finding(s)	
TRIANGLE TOOL TO TPA	[]pre-existing cond chked	
-1113	[]not inspetd this patrol	
	Notes:	
38.477965000000	12 KU	
-121.7958100000	No 3. FOUT	
019/417 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40816601	[ ]completed/new finding(s)	
TOL DIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
70. 4FF9F999999	Notes: W	
38.477378000000	NO B. BODS	
-121.7963210000		Troba) # of Astrobasta
A003/079 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40768140 FLAT PIN ARM	[]completed/new finding(s)	
LACL FIN SITT	[]not inspctd this patrol	
	Notes: '02 Survey: C015954	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
38.385685000000	modes. Tog Burvey: CO15954	
-1,21,8777960000		

Page 53

Inspector Name : __ Date Inspected : _

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A003/080 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40767520	[]completed/new finding(s)	
TRI PIN ARM DEAD END	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015955	
38.385176000000	noces: 02 Sarvey. Colssis	
-121.8782310000		
A004/081 SINGLE WOOD POLE SW 49	(Xcompleted/no problems	Total # of Attachments:
40817778	[]completed/new finding(s)	
FIELD SWITCH STRUCTURE	()pre-existing cond chked	
321002010	[] not inspetd this patrol	
	Notes:	
38.384753000000	WOLES:	
-121.8786220000		
	1/12	
A004/082 SINGLE WOOD POLE	Ylcompleted/no problems	Total # of Attachments:
408 <b>23472</b>	[]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015957	
38.384243000000		
-121.8790800000		
A004/083 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40869030	[ ]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ] not inspetd this patrol	
	Notes: '02 Survey: C015958	
38.383679000000		
-121.8795750000		
A004/084 SINGLE WOOD POLE	sompleted/no problems	Total # of Attachments:
40874383	[]completed/new finding(s)	
3 HORIZONTAL POST DELTA SHORT	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015959	
38.383084000000		
-121.880083 <b>00</b> 00		
A004/085 SINGLE WOOD POLE		Total # of Attachments:
40601259	[ ]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015960	
38.38249900000		
-121.8806150000		
A004/086 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
41122286	completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015961	
38.381897000000		
-121.8811540000		
004/087 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
10592640	[]completed/new finding(s)	a see the transfer of
· · · · · · · · · · · · · · · · · · ·	[ ]pre-existing cond chked	
TRI POST		
FRI POST		
TRI POST	[ ]not inspetd this patrol	
TRI FOST 38.381290000000		

Page 54

Inspector Name : COOPEK Date Inspected : _

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		Accountant Type, owner wisced
Access:		
HOST Tech ID/Equip #:	Notes	L,,
Lat:	Notes	
Long:		
A004/088 SINGLE WOOD POLE	1/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2	Im . 1 III C
4	completed/no problems	Total # of Attachments:
40677818	[]completed/new finding(s)	
TO POST ( )	[ ]pre-existing cond chked	
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015963	
38.380695000000		
-121.8821830000	<u> </u>	
A004/089 SINGLE WOOD POLE	[ completed/no problems	Total # of Attachments:
40665500	[]completed/new finding(s)	
TRI FOST (-(C)	[ ]pre-existing cond chked	
' " '	[]not inspetd this patrol	
	Notes: '02 Survey: C015964	
38.380245000000		
-121.8825890000		
A004/090 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40768158	[]completed/new finding(s)	DIST-0310456 1
TPI POST	[ ]pre-existing cond chked	
`	[ ] not inspctd this patrol	
	Notes: '02 Survey: C015965	
38.380038000000		
-121.8827590000		
A004/091 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40767500	[ ]completed/new finding(s)	
TRI FOST (C)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
•	Notes: '02 Survey: C015966	
38.379525000000		•
-121.8832790000		
A004/092 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40817780	[ ]completed/new finding(s)	
TRI-POST- / ((C)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
`	Notes: '02 Survey: C015967	
38.378931000000	_	
-121.8837800000		
A004/093 SINGLE WOOD POLE		Total # of Attachments:
40823470	[]completed/new finding(s)	
40823470 RT POST (NC)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
,	Notes: '02 Survey: C015968	
38.378333000000		
-121.8843000000		
DOCK / DOK STREET WOOD BOLE	completed/no problems	Total # of Attachments:
40875452 TRI POST	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
	[] not inspetd this patrol	
,	Notes: '02 Survey: C015969	
38.377746000000		
-121.8848280000		
A004/095 SINGLE WOOD POLE	completed no problems	Total # or Actachments:
40868364	[]completed/new finding(s)	
	[]pre-existing cond chked	
TRI DOST T-1(C)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015970	
38.377127000000	Moces: -02 autvey: Coisa/0	
-121.8853990000		
-121.0053330000		

Inspector Name : COOVEV Date Inspected: 3-19-12

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

: 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	. /	
A004/096 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40612577	[]completed/new finding(s)	
TRI POST T-(C)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015971	•
38.376540000000		
-121.8859100000		
A004/097 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40592642 TRI POST (C)	[]completed/new finding(s) []pre-existing cond chked	
1200	-	
	[ ]not inspctd this patrol Notes: '02 Survey: C015972	
38.375998000000	Notes: 102 survey: CUIS972	,
-121.8863920000		
A004/098 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40695439	[]completed/new finding(s)	
TRI BOOT (-1(c)	[]pre-existing cond chked	
	[]not inspctd this patrol	
İ	Notes: '02 Survey: C015973	<u> </u>
38.375362000000		
-121.8869560000		
A004/099 SINGLE WOOD POLE	recompleted/no problems	Total # of Attachments:
40665485	[]completed/new finding(s)	
3 HORIZONTAL POST DELTA SHORT	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015974	
38.374741000000		
-121.8875160000		
A004/100 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40759930	[ ]completed/new finding(s)	
1 <del>72 1001 </del> T-1(C)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
30 3743 54000000	Notes: '02 Survey: C015975	
38.374164000000 -121.8880300000		
A004/101 SINGLE WOOD POLE	[ completed/no problems	Total # of Attachments:
4000000	[] completed/new finding(s)	
THE POST T-1 (NC)	[]pre-existing cond chked	
(-\ (N°)	[]not inspetd this patrol	
	Notes: '02 Survey: C015976	
38.373597000000	32 247.7	
-121.8885600000	1 7 7 7 7 7	
A005/102 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40817782	[ ]completed/new finding(s)	
TRI POST T-1(C)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015977	
38.373005000000		
-121.8890820000		
A005/103 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40816647	completed/new finding(s)	
THE POST (NIC)	[ ]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015978	1
24 25041602222		
38.372416000000 -121.8896040000		

Inspector Name : COOPER Date Inspected : _

Funct Loc : ETL.6740.POLE_WOOD

60067 DIXON-VACA #2+-WOOD POLE

: 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Indeposition Popult	17th admonta #
Equip #	Inspection Result	Attachments # Attachment Type/Owner Listed
Framing Config		Attachment Type/Owner Listed
Access:		<u> </u>
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A005/104 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40869032	[ ]completed/new finding(s)	
	[ ]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C015979	
38.371842000000		
-121.8901470000		
A005/105 SINGLE WOOD POLE	>==completed/no problems	Total # of Attachments:
40874369	[ ]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015980	
38.371216000000		
-121.8906670000		
A005/106 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40612567	Trampleted/new finding(s)	<del>                                     </del>
	[ ]pre-existing cond chked	
TOUR TOUR	[]not inspetd this patrol	Brokes INSU'S KPIN - N. Phase.
	Notes: '02 Survey: C015981	0 1 1 1 10 14 1 100
38.370593000000	1.00031	
-121.8912310000		
A005/107 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
4059936 <b>5</b>	[]completed/new finding(s)	l l
SOT DOOR	[]pre-existing cond chked	
T-I (N/C)	[ ]not inspetd this patrol	
, , , ,	Notes: '02 Survey: C015982	
38.370048000000	100ces: 02 Survey: C013382	
-121.8917130000		
A005/108 SINGLE WOOD POLE		Total # of Attachments:
40695406	[ ]completed/new finding(s)	
	[ ]pre-existing cond chked	
TRI DOOT (C)	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015983	
30 76070400404	100ces: '02 Survey: C015983	
38.369398000000		
-121.8922370000		
A005/109 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40665477	[]completed/new finding(s)	
TRI FOST T-1(C)	[]pre-existing cond chked	
	[]not inspctd this patrol	
20 2000000000	Notes: '02 Survey: C015984	
38.36882800000		
-121.8927510000		
A005/110 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40759932	[]completed/new finding(s)	
T-1(4)	[]pre-existing cond chked	
(	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015985	
38.368224000000		
-121.8932580000		
A005/111 SINGLE WOOD POLE		Total # of Attachments:
40767488	[ ]completed/new finding(s)	
TRI FOST ( ( C )	[ ]pre-existing cond chked	
	[ ] not inspetd this patrol	
	Notes: '02 Survey: C015986	
38.367613000000		
-121.8938180000		

Inspector Name : COOPER Date Inspected : _3

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A005/112 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40817784	[ ]completed/new finding(s)	
TPI BOOM (C)	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015987	
38.367034000000		
-121.8943290000		
A005/113 SINGLE WOOD POLE		Total # of Attachments:
40823443	[ ]completed/new finding(s)	
1-1(c)	[ ]pre-existing cond chked	
	[]not inspctd this patrol	
38.366317000000	Notes: '02 Survey: C015988	
1		
-121.8949920000 A005/114 SINGLE WOOD POLE	V Kommissadina	
40869034	completed/no problems	Total # of Attachments:
	[]completed/new finding(s)	
(-1(c)	[ ]pre-existing cond chked	
- \- \ -	[ ]not inspetd this patrol Notes: '02 Survey: C015989	
38.365849000000	Noces: -02 Survey: C015989	
-121.8954190000		
A005/115 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40874367	[]completed/no problems	TOTAL # OI ACCACAMENTS:
3 HORIZONTAL POST DELTA	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015990	
38.365269000000		
-121.8958990000		
A005/116 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40601262	[]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015991	
38.364657000000		
-121.8964260000		
A005/117 SINGLE WOOD POLE		Total # of Attachments:
40599363	[ ]completed/new finding(s)	
T-1(c)	[ ]pre-existing cond chked	
( ) ( )	[ ]not inspctd this patrol	
	Notes: '02 Survey: C015992	
38.364334000000		
-121.8967080000	1 2	
A005/118 SINGLE WOOD POLE		Total # of Attachments: 1
10695435	[]completed/new finding(s)	FIBR-UNNOWN 1
TRI POST	[ ]pre-existing cond chked	
	[]not inspetd this patrol	
P 3640648888800	Notes: '02 Survey: C015993	
131 8868732000		
121.8969720000		
005/119 SINGLE WOOD POLE		Total # of Attachments: 1
10665475	[ ]completed/new finding(s)	FIBR-UNKNOWN 1
CRI POST	[ ]pre-existing cond chked	
	[]not inspetd this patrol	The control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the co
29 262500000000	Notes: '02 Survey: C015994	
8.363502000000 121.8975040000		

Page 58

Inspector Name : Cooper

Date Inspected: 3-28-(7

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

: 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config	1	
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	17	
A005/120 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40759934	[]completed/new finding(s	
TRI POST	[ ]pre-existing cond chked	•
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C015995	
38.362989000000	noces. oz sarvey. corsyy	
-121.8979610000		
A005/121 SINGLE WOOD POLE		Total # of Attachments: 1
40767486	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
1112 2001	[]not inspetd this patrol	
	Notes: '02 Survey: C015996	
38.362487000000	mores: .os anticeà: corpage	
-121.8983800000	×	
A005/122 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40825139	[]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	· ·
	[ ]not inspctd this patrol	
	Notes: 102 Survey: C015997	
38.361765000000		
-121.8990010000	1	
A006/123 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
10823455	[ ]completed/new finding(s)	
TRI POST	pre-existing cond chked	1
	[ ]not inspetd this patrol	1 7 - 3 1 - 1 -
	Notes: '02 Survey: G015996	
38.361075000000		
-121.8996160000		
A006/124 SINGLE WOOD POLE	[ ]completed/no problems	Total # of Attachments: 1
4086903 <b>6</b>	[ ]completed/new finding(s)	
TRI POST	pre-existing cond chked	
	[ ]not inspetd this patrol	LEANING POLC
	Notes: '02 Survey: C015999	)
38.360497000000		
121.9001440000		
A006/125 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
10874365	[ ]completed/new finding(s)	
TRI POST	pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C016000	The state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the s
8.359913000000	72 302 43 2 2010000	
121.9006320000		
1006/126 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
10601265	[]completed/new finding(s)	
RI POST	[]pre-existing cond chked	TIM ONITIONAL I
.RI 1001	[] not inspetd this patrol	
	Notes: '02 Survey: C016001	
35950000000	mores: .ox survey: coleont	
121.9011000000		
1006/127 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
10592643	[]completed/new finding(s)	
RI POST	pre-existing cond chked	1/500
	[ ]not inspctd this patrol	heaving Pola
	Notes: '02 Survey: C016002	
38.358993000000		
-121.9014910000	1	

Inspector Name : Cooper Date Inspected : 3,

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A006/128 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40677822	[]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
1001	[] not inspetd this patrol	
	Notes: '02 Survey: C016003	
38.358730000000	Roces: '02 Survey: C016003	
-121.9017240000		
A006/129 SINGLE WOOD POLE	1	
40599362	completed/no problems	Total # of Attachments: 1
	[]Completed/new finding(s)	FIBR-UNKNOWN 1
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016004	
38.358133000000		
-121.9022380000		
A006/130 SINGLE WOOD POLE	//completed/no problems	Total # of Attachments: 1
40695373	[ ]completed/new finding(s)	
TRI POST	[ lpre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016005	
38.357575000000		
121.9027670000		
006/131 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
0657554	[ completed/new finding(s)	
RI POST		FIBR-UNKNOWN I
RI FOSI	[ ]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C016006	
38.356974000000		
-121.9032510000	1	
1006/132 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
10768115	[ ]completed/new finding(s)	FIBR-UNKNOWN 1
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016007	
8.356378000000		
121.9038000000		
006/133 SINGLE WOOD POLE	completed/no problems	Total # or Attachments: 1
0759688	[]completed/new finding(s)	
HORIZONTAL POST DELTA SHORT	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016008	
8.355764000000	noces. 02 Salvey: Colour	
121.9043450000		
006/134 SINGLE WOOD POLE	N. Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Complete and Co	
006/134 SINGLE WOOD POLE 0825133	completed/no problems	Total # of Attachments: 1
· -	( completed/new finding(s)	FIBR-UNKNOWN 1
RI POST	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C016009	
3.355094000000		
121.9049290000		
006/135 SINGLE WOOD POLE		Total # of Attachments: 2
0823453	[ ]completed/new finding(s)	DIST-0310456 1; FIBR-UNKNOWN 1
RI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	I Thou inspects this pation i	
	Notes: '02 Survey: C016010	
8.35460000000		

Inspector Name : Cooper

Date Inspected : 3-28-12

Funct Loc: ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		1/Po/ 0.1102 215000
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A006/136 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 2
40875432		DIST-0310456 1; FIBR-UNKNOWN 1
TRI POST	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C016011	
38.35398400000	noces. of burvey. consort	
-121.9058970000		
A006/137 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 2
40868366		DIST-0310456 1; FIBR-UNKNOWN 1
ANGLE 0-30 DEGREES	[]pre-existing cond chked	John College Ly Link-dilligation L
	( )not inspetd this patrol	
	Notes: '02 Survey: C016012	
38.353616000000	Va 522.0y. 6020012	
-121.9061300000		
A006/138 SINGLE WOOD POLE	lcompleted/no problems	Total # of Attachments: 2
40612555		DIST-0310456 1; FIER-UNKNOWN 1
TRI POST	[]pre-existing cond chked	STATE OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK OF THE TANK
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016013	<u> </u>
38.35320000000	Notes: 02 Survey: Colours	
-121.9060920000		
A006/139 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 2
40599379		DIST-0310456 1; FIBR-UNKNOWN 1
TRI POST	[]pre-existing cond chked	DIST-0310436 I; FIBR-UNKNOWN I
INI POSI	[]not inspetd this patrol	
	Notes: '02 Survey: C016014	
38.352527000000	Modes: '02 Survey: C016014	
-121.9060760000		
A006/140 SINGLE WOOD POLE	X]completed/no problems	Total # of Attachments: 2
10695369	_	DIST-0310456 1; FIBR-UNKNOWN 1
TRI POST	[]pre-existing cond chked	DISK-0310430 I; FIBR-UNANUWN I
	[] not inspetd this patrol	
	Notes: '02 Survey: C016015	
88.351891000000	Notes: '02 survey: Colsols	
121.906100000		
A006/141 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 3
10657556		DIST-0310456 1; FIBR-UNKNOWN 1; STLT-UNKNOWN 1
TRI POST	[]pre-existing cond chked	2201-0320430 I) FIRE-UNINOWN I; STEE-UNINOWN I
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016016	STREET LIGHT
88.351543000000	Lines of parter. Colours	
121.9062110000		
006/142 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 3
0759936		DIST-0310456 1; FIBR-UNKNOWN 1; PHON-UNKNOWN 1
RI POST	[]pre-existing cond chked	SECT OF TOTAL ON THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE SECTION OF THE
	[] not inspetd this patrol	
	Notes: '02 Survey: C016017	
8.351313000000	Ja Burvey: Coldul	
121.9062460000		
006/143 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 3
0759690		DIST-0310456 1; FIBR-UNKNOWN 1; PHON-UNKNOWN 1
	pre-existing cond chked	THE THE TANK WARMONN I, FROM CHRONOWN I
R.L. POST	The charactery court cured	(1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1
RI POST	I lnot inspetd this patrol	Y MAR AND LANGE
RI POST	[]not inspetd this patrol	LEDIALE TOLE
RI FOST 8.350994000000	[ ]not inspetd this patrol Notes: '02 Survey: C016018	* Replace fole

Inspector Name : Coopek

Date Inspected : 3-28-12

Medium Impact

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	•	Attachment Type/Owner Listed
Framing Config		I I I I I I I I I I I I I I I I I I I
Access:		
	W-1	
HOST Tech ID/Equip #:	Notes	
Lat:		•
Long:		
A006/144 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 3
40825141	[ ]completed/new finding(s)	DIST-0310456 1; FIBR-UNKNOWN 1; PHON-UNKNOWN 1
TRI POST	[ ]pre-existing cond chked	The state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the s
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016019	<u> </u>
38.350581000000	Noces. Va Burvey: CO16013	
-121.9068830000		
A006/145 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 4
40816649	[ ]completed/new finding(s)	DIST-0310456 2; FIBR-UNKNOWN 1; PHON-UNKNOWN 1
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016020	
38.350302000000	,	
-121.9071680000		
A006/146 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 3
40875430		DIST-0310456 2; FIER-UNKNOWN 1
TRI POST		DIST-0310456 2; FIBR-UNKNOWN 1
IRI POSI	[ ]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C016021	
38.349923000000		
-121.9075730000	6	
A006/147 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 4
40868368	[ ]completed/new finding(s)	DIST-0310456 2; FIBR-UNKNOWN 1; PHON-UNKNOWN 1
TRI POST	[]pre-existing cond chked	2 TO TO TO STAND STAND STAND STAND STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS STANDS ST
	[] not inspetd this patrol	
	Notes: '02 Survey: C016022	
38.349633000000	Noces: '02 Survey: C016022	
-121.9077420000		
A007/148 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 5
40612552	[ ]completed/new finding(s)	DIST-0310456 2; FIBR-UNKNOWN 1; PHON-UNKNOWN 1; STLT-UNKNOWN 1
TRI POST	[ ]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C016023	STREET LIGHT
38.349320000000	1	
-121.9080070000		
A007/149 SINGLE WOOD POLE	Ncompleted/no problems	mate 1 at a 5 phone leaves
10592645		Total # of Attachments: 3
		DIST-0310456 2; FIBR-UNKNOWN 1
FRÏ POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016024	
38.348887000000		
121.9083170000		
A007/150 SINGLE WOOD POLE	X completed/no problems	Total # of Attachments: 5
0695365		DIST-0310456 2; FIBR-UNKNOWN 1; PHON-UNKNOWN 1; STLT-UNKNOWN 1
RI POST	[]pre-existing cond chked	TILLION D, LAME OF LIGHT L, FROM OFFICION I; SIET-UNKNOWN I
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016025	CONTRACT TOUR
9 349493000000	notes: -02 Survey: C016025	SIREET LIGHT
8.348493000000		
121.9086470000		
007/151 SINGLE WOOD POLE		Total # of Attachments: 3
0657558	[]completed/new finding(s)	DIST-0310456 1; FIER-UNKNOWN 1; STLT-UNKNOWN 1
RI POST	[ ]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C016026	STREET LIGHT
88.34812400000		
121.9090980000		
	,	

Inspector Name : Date Inspected : 3-2

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A007/152 SINGLE WOOD POLE		Total # of Attachments: 3
40768138	filesmoleted/now finding/el	DIGHT # OF ATTRONES: 3
DOUBLE VERTICAL	[]pre-existing cond chked	DIST-0310456 1; FIBR-UNKNOWN 1; STLT-UNKNOWN 1
	[ ]not inspctd this patrol	
38.347694000000	Notes: '02 Survey: C016027	STREET LIGHT
-121.9094020000		
A007/153 SINGLE WOOD POLE		Total # of Attachments: 1
40759692	[ ]completed/new finding(s)	FIBR-UNKNOWN 1
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C016028	
38.347774000000		
-121.9097330000	<b> </b> ✓	
A007/154 SINGLE WOOD POLE	/ ]completed/no problems	Total # of Attachments: 1
40825131	[ ]completed/new finding(s)	PTRR-INKNOWN 1
TRI POST	[]pre-existing cond chked	AND AND AND T
	[]not inspetd this patrol	
	Notes: '02 Survey: C016029	
38.347890000000	Motes: 02 Survey: C016029	
-121.9106250000		
A007/155 SINGLE WOOD POLE	[]completed/no problems	
10816651		Total # of Attachments:
OUBLE VERTICAL	[]completed/new finding(s)	
SOUBLE VERTICAL	Apre-existing cond chked	
	[ ]not inspctd this patrol	Trestall Sluwes ouce Cuy Autospice
	Notes: '02 Survey: C016030	7,000 SP 110
38.347981000000		
-121.9111870000		
1007/156 SINGLE WOOD POLE		Total # of Attachments:
11122288	[ ]completed/new finding(s)	
	[ ]pre-existing cond chked	
	I Tare-evracting cond dived	
		<b>1</b>
T-1(°)	[ ]not inspetd this patrol	*
7-1(0)		*
8.34743000000	[ ]not inspetd this patrol	*
8.347430000000 121.9116820000	[ ]not inspctd this patrol Notes: '02 Survey: C016031	Total # of Newshard
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE	[] not inspctd this patrol Notes: '02 Survey: C016031	Total # of Attachments:
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s)	Total # of Attachments:
88.347430000000 -121.9116820000 -007/157 SINGLE WOOD POLE -1122290	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked	
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290 PLI POST	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290 PT DOST	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked	
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290 BI DOST (8.346926000000	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	
8.34743000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290 PLI POST (C) 3.346926000000 121.9121810000	[] not inspctd this patrol Notes: '02 Survey: C016031  [] Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032	Total # OF Attachments:  **Re-ATTACHED Phi = Fiber Optic  To Pole.
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290 RI POST (C) 8.346926000000 121.9121810000 007/158 SINGLE WOOD FOLE	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	* Re-ATTACHED PLY E FIBER OPTIC
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290 ET POST  (C) 8.346926000000 121.9121810000 007/158 SINGLE WOOD FOLE	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032	
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290 PI POST  (C) 8.346926000000 121.9121810000 007/158 SINGLE WOOD FOLE	[] not inspctd this patrol Notes: '02 Survey: C016031  [] Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032	* RE-ATTACHED PLY = FIBER OPTIC
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290 RT POST  8.346926000000 121.9121810000 007/158 SINGLE WOOD POLE 0592646 RT POST	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked	* Re-ATTACHED PLE E FIBER OPTIC
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290 PI POST  (C) 8.346926000000 121.9121810000 007/158 SINGLE WOOD FOLE	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	* Re-ATTACHED PLE E FIBER OPTIC
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290 PI POST  8.346926000000 121.9121810000 007/158 SINGLE WOOD FOLE 0592646 PI POST	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked	* Re-ATTACHED PLE E FIBER OPTIC
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290 ET POST  8.346926000000 121.9121810000 007/158 SINGLE WOOD FOLE 0592646 ET POST	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	* Re-ATTACHED PLE E FIBER OPTIC
8.347430000000 121.9116820000 .007/157 SINGLE WOOD POLE 1122290 EL POST  6.346926000000 121.9121810000 007/158 SINGLE WOOD FOLE 0592646 EL POST  (C) 8.346342000000 121.9127240000	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016033	RE-ATTACHED Phi E FIBER OPTIC TO POLE. TOtal # of Attachments:
8.347430000000 121.9116820000 1007/157 SINGLE WOOD POLE 1122290 ET POST  8.346926000000 121.9121810000 007/158 SINGLE WOOD FOLE 0592646 ET POST	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016033  [] completed/no problems [] completed/no problems	* Re-ATTACHED PLE E FIBER OPTIC
8.347430000000 121.9116820000 1007/157 SINGLE WOOD POLE 1122290 1122290 121.9121810000 121.9121810000 1007/158 SINGLE WOOD FOLE 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016033  [] completed/no problems [] completed/no problems [] completed/no problems [] completed/no problems [] completed/no problems [] completed/no problems [] completed/new finding(s)	RE-ATTACHED Phi E FIBER OPTIC TO POLE. TOtal # of Attachments:
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290 ET POST  8.346926000000 121.9121810000 007/158 SINGLE WOOD FOLE 0592646 ET POST  C) 3.346342000000 121.9127240000 007/159 SINGLE WOOD POLE	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016033  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] loompleted/new finding(s) [] pre-existing cond chked	RE-ATTACHED Phi E FIBER OPTIC TO POLE. TOtal # of Attachments:
8.347430000000 121.9116820000 007/157 SINGLE WOOD POLE 1122290 ET POST  8.346926000000 121.9121810000 007/158 SINGLE WOOD FOLE 0592646 ET POST  C) 3.346342000000 121.9127240000 007/159 SINGLE WOOD POLE	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016033  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	RE-ATTACHED Phi E FIBER OPTIC TO POLE. TOtal # of Attachments:
38.347430000000 -121.9116820000 A007/157 SINGLE WOOD POLE H1122290 PRI POST	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016033  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] loompleted/new finding(s) [] pre-existing cond chked	RE-ATTACHED Phi E FIBER OPTIC TO POLE. TOtal # of Attachments:
8.347430000000 121.9116820000 1007/157 SINGLE WOOD POLE 1122290 1122290 121.9121810000 121.9121810000 1007/158 SINGLE WOOD FOLE 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646 10592646	[] not inspctd this patrol Notes: '02 Survey: C016031  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016032  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C016033  [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	RE-ATTACHED Phi E FIBER OPTIC TO POLE. TOtal # of Attachments:

Inspector Name : COOPER Date Inspected : 3-2

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		TE-, Character Transport
Access:	1	
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A007/160 SINGLE WOOD POLE	completed/no problems	Potent # of Attochmonts
40665473	[]completed/new finding(s)	Total # of Attachments:
1-49	[]pre-existing cond chked	
, - '	[]not inspctd this patrol	
32 24514000000	Notes: '02 Survey: C016035	
38.345149000000		
-121.9137450000		
A007/161 SINGLE WOOD POLE	recompleted/no problems	Total # of Attachments:
40768130	[]completed/new finding(s)	
(C)	[]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016036	
38.344576000000		
-121.9142740000		
A007/182 SINGLE WOOD POLE	ficompleted/no problems	Total # of Attachments:
40767483	[ ]completed/new finding(s)	Í
3 HORIZONTAL POST DELTA SHORT	[ ]pre-existing cond chked	
3445	[ ]not inspetd this patrol	
1	Notes: '02 Survey: C016037	
38.343991000000		
-121.9148100000		
A007/183 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40817786	[]completed/new finding(s)	
(C)	[ ]pre-existing cond chked	i
イーベン	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016038	
38.343545000000		
-121.9151840000		
A007/164 SINGLE WOOD POLE	Acompleted/no problems	Total # of Attachments:
40823442	[] completed/new finding(s).	
	[]pre-existing cond chked	
TRI BOOT (C)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016039	
38.342928000000	Noces: '02 Survey: C016039	
-121.9157440000		
	1	
A007/165 SINGLE WOOD POLE		Total # of Attachments:
40875436	[]completed/new finding(s)	
TPI POST 1(C)	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016040	
38.342632000000		
-121.9159730000		
A007/166 SINGLE WOOD POLE		Total # of Attachments:
40874363	[]completed/new finding(s)	
TRI POST (C)	[ ]pre-existing cond chked	
7-11.	[ ]not inspctd this patrol	
	Notes: '02 Survey: C016041	
38.342015000000		
-121.9165270000		
A007/167 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40601267	[ ]completed/new finding(s)	A TOTAL STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF T
TRE DOST	[ ]pre-existing cond chked	
~-1(c)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016042	
38.341395000000	Da burvey: Colouda	Í
-121.9170350000	i de la companya de la companya de la companya de la companya de la companya de la companya de la companya de	

Inspector Name : Date Inspected : _

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A007/168 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40599360	[]completed/new finding(s)	
3 HORIZONTAL POST DELTA SHORT	[]pre-existing cond chked	
	[ ]not inspetd this patrol	•
	Notes: '02 Survey: C016043	
38.34076900 <b>00</b> 00	Notes: -02 Survey: C016043	
-121.9176070000		
A007/169 SINGLE WOOD POLE	[	Image 2 in Contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the contract to the con
40677826		Total # of Attachments:
TRI POST	[]completed/new finding(s)	
- VCA	[]pre-existing cond chked	
てーじょ	[]not inspetd this patrol	
70 0400400000	Notes: '02 Survey: C016044	
38.34024000000		
-121.9180670000		
A007/170 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40665469	[ ]completed/new finding(s)	
TRI-POST	[ ]pre-existing cond chked	
` イー(C)	[ ] not inspctd this patrol	
	Notes: '02 Survey: C016045	
38.339618000000		
-121.9186460000		
A007/171 SINGLE WOOD POLE	Decompleted/no problems	Total # of Attachments:
40759938	[ ]completed/new finding(s)	
TRE POST	[]pre-existing cond chked	
	[ ]not inspetd this patrol	
T-40)	Notes: '02 Survey: C016046	
38.33896900000	12 201 vey: C016046	
-121.919200000		
A007/172 SINGLE WOOD POLE		Total # AF Total
40767480	[]completed/new finding(s)	Total # of Attachments:
TRE POST		
	[]pre-existing cond chked	
T-((°)	( )not inspetd this patrol	
20. 22022.400	Notes: '02 Survey: C016047	
88.33837400000		
121.9197410000		
A007/173 SINGLE WOOD POLE		Total # of Attachments:
0817788	completed/new finding(s)	
RI POST	[ ]pre-existing cond chked	V 11/100
1-1-1	[ ]not inspctd this patrol	* Missing Crossing MARKER
	Notes: '02 Survey: C016048	
8.337812000000		
121.9202320000		
008/174 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
0823468	[]completed/new finding(s)	DIST-0310456 1
# 2000 (C)	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C016049	
8.337249000000	Darvey: Corects	
121.9207130000		
008/175 SINGLE WOOD POLE	appalated/s	
0869038		Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
EI BOST	[]pre-existing cond chked	
•	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016050	
8.336580000000		
121.9213590000		

Inspector Name : Coopen Date Inspected: 3-23-

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Inspection Result	Attachments #
	Attachment Type/Owner Listed
Notes	
Completed/no problems	Total # of Attachments: 1
	DTST-02104EC 1
Moces: 02 Survey: COIPOST	
[ lassisted/no problems	Total # of Attachments: 1
[ ] completed/new finding(s)	DIST-0310456 1
I not inspetd this patrol	
Notes: '02 Survey: C016052	
}	
**Completed/no problems	Total # of Attachments: 1
[ ]completed/new finding(s)	DIST-0310456 1
[ ]not inspctd this patrol	
Notes: '02 Survey: C016053	
Completed/no problems	Total # of Attachments: 1
	DIST-0310456 1
[ ]pre-existing cond chked	
Notes: '02 Survey: C016054	
Dompleted/no problems I	Total # of Attachments: 1
[]completed/new finding/el	DIST-0310/66 1
	2007-02T0430 T
Completed/se seekiles	
	Total # of Attachments: 1
	DIST-0310456 1
Notes: '02 Survey: C016056	
	Total # of Attachments: 1
[ ]completed/new finding(s) [	DIST-0310456 1
completed/no problems 3	Total # or Attachments: 1
	DIST-0310456 1
[ ]pre-existing cond chked	
Shight h	
	Notes    Completed/no problems

Page 66

Medium Impact

Inspector Name : Cooper

Date Inspected: ___

Funct Loc : ETL.6740.POLE.WOOD

: 41620567

PATR/INSP 60067 DIXON-VACA #2+

60067 DIXON-VACA #2+-WOOD POLE

Detailed Ground Inspections

Desc of Tech ID Inspection Result Attachments # Equip # Attachment Type/Owner Listed Framing Config Access: Notes HOST Tech ID/Equip #: Lat: Long: A008/184 SINGLE WOOD POLE Completed/no problems Total # of Attachments: 1 40868370 []completed/new finding(s) DIST-0310456 1 [ ]pre-existing cond chked [ ]not inspctd this patrol Notes: '02 Survey: C016059 38.331003000000 -121.9263830000 A008/185 SINGLE WOOD POLE ► completed/no problems Total # of Attachments: 1 [ ]completed/new finding(s) DIST-0310456 1 **** ***** (-/ (ト/c) [ ]pre-existing cond chked [ ]not inspctd this patrol Notes: '02 Survey: C016060 38.330403000000 -121.9269190000 A008/186 SINGLE WOOD POLE empleted/no problems Total # of Attachments: 1 [ ]completed/new finding(s) DIST-0310456 1 [ ]pre-existing cond chked 191 [ ]not inspetd this patrol Notes: '02 Survey: C016061 38.329750000000 -121.9274760000 completed/no problems A008/187 SINGLE WOOD POLE Total # of Attachments: 1 40677835 [ ]completed/new finding(s) DIST-0310456 1 [ ]pre-existing cond chked シントンド [ ]not inspctd this patrol Notes: '02 Survey: C016062 38.329231000000 -121.9279340000 A008/188 SINGLE WOOD POLE completed/no problems Total # of Attachments: 1 40665467 [ ]completed/new finding(s) DIST-0310456 1 [ lpre-existing cond chked [ ]not inspetd this patrol Notes: '02 Survey: C016063 38.328614000000 -121.9284640000 A008/189 SINGLE WOOD POLE completed/no problems [ ]completed/new finding(s) [ ]pre-existing cond chked [ ]not inspetd this patrol Notes: '02 Survey: C016064 38.328054000000 -121.9290160000 A008/190 SINGLE WOOD POLE completed/no problems 40767477 []completed/new finding(s) [ ]pre-existing cond chked [ ]not inspetd this patrol Notes: '02 Survey: C016065 38.327409000000 -121,9295830000 A008/191 SINGLE WOOD POLE *completed/no problems Total # of Attachments: [ ]completed/new finding(s) [ ]pre-existing cond chked [ ]not inspctd this patrol Notes: '02 Survey: C016066 ble Has "E" Truss 38.326824000000 -121.9300770000

Page 67

Date Inspected:

Inspector Name : COOPEN

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		TIPO TIPO TIPO TIPO TEL
Access:	i .	
HOST Tech ID/Equip #:	Notes	
Lat:	Noces	
Long:		
A008/192 SINGLE WOOD POLE	466	
40823440	completed/no problems	Total # of Attachments:
TRI POST	[ completed/new finding(s)	
IRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	<u></u>
	Notes: '02 Survey: C016067	
38.326234000000		
-121.9306140000		
A009/193 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40869042	[ ]completed/new finding(s)	
TRI POST / - YC)	[ ]pre-existing cond chked	
TEL-POST (C)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016068	
38.325672000000		
-121.9311310000		
A009/194 SINGLE WOOD POLE	rcompleted/no problems	Total # of Attachments:
40874361	[ ]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C016069	
38.325039000000	Modes: .02 adivey: C018089	
-121.9316290000		
A009/195 SINGLE WOOD POLE		
10601 270		Total # of Attachments:
TRI POST	[ ]completed/new finding(s)	
	[ ]pre-existing cond chked	
·	[ ]not inspetd this patrol	
•• ••••	Notes: '02 Survey: C016070	
38.324454000000		•
-121.9321860000		
1009/196 SINGLE WOOD POLE	recompleted/no problems	Total # of Attachments:
10599357	[ ]completed/new finding(s)	
VERTICAL SHORT POST	[ ]pre-existing cond chked	
34800)	[ ]not inspetd this patrol	
21134	Notes: '02 Survey: C016071	
8.32390000000		
121.9327480000		
009/197 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
059938 <b>0</b>	[   completed/new finding(s)	
TRI FOST	I pre-existing cond chked	
1-1(c)	[ ]not inspctd this patrol	
1-11	Notes: '02 Survey: C016072	
8.323310000000	52 241 eg. C010072	
121.9332620000		
009/198 SINGLE WOOD POLE	impleted/no problems	Total # of Attachments:
0695356		TOTAL # OF WEEGCURENES:
	[]pre-existing cond chked	
4-1(C)		
	[]not inspetd this patrol	
322540000000	Notes: '02 Survey: C016073	
31 9339550000		
21.9338660000		
009/199 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0665465	[ ]completed/new finding(s)	
RI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016074	
3.322382000000		

Page 68

Inspector Name : COOPER

Date Inspected : 2-24-12

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		The state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the s
Access:		
OST Tech ID/Equip #:	Notes	
lat:	Noces	
Long:		
A009/200 SINGLE WOOD POLE	1completed/no problems	Im-1-1 H = C 2 ( ) 1
•		Total # of Attachments:
40768124	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C016075	
38.321806000000		"c" Truss
-121.9345330000	YOLE HAS	
A009/201 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
10759694	[ ]completed/new finding(s)	·
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016076	
19.321250000000		
-121.9350620000		
A009/202 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40825129	[ ]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016077	
8.320653000000		
121.9355620000		
009/203 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
.0816653	[]completed/new finding(s)	· ·
RI POST	[]pre-existing cond chked	
RI POSI		
	[ ] not inspetd this patrol	
	Notes: '02 Survey: C016078	
8.319992000000		
121.9361230000		
009/204 SINGLE WOOD POLE	templeted/no problems	Total # of Attachments:
0875429	[ ] completed/new finding(s)	
RI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016079	
8.319407000000		
121.9366990000	= /	
009/205 SINGLE WOOD FOLE	(xcompleted/no problems	Total # of Attachments:
0868372	[ ]completed/new finding(s)	
RI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016080	
8.31879900000	-	
121.9371750000		
009/206 SINGLE WOOD POLE		Total # of Attachments:
0601275	[ ]completed/new finding(s)	
RI POST	[]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016081	
8.318246000000	words. or pervel; coragar	
121.9376920000		
009/207 SINGLE WOOD POLE	I completed (see such less	Total # of 7th admonts.
· ·	Completed/no problems	Total # of Attachments:
0599356	[]completed/new finding(s)	
RI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016082	
8.317655000000		
121.9382390000		

Inspector Name : COOPER Date Inspected: 2-24-12

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A009/208 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40677839	[]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
İ	[ ]not inspctd this patrol	
	Notes: '02 Survey: C016083	
38.317080000000		
<u>-</u> 121.9387400000		
A009/209 SINGLE WOOD POLE	rempleted/no problems	Total # of Attachments:
40665496	[   completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
1	[ ]not inspctd this patrol	
	Notes: 102 Survey: C016084	I
38.316515000000		
-121.9392310000		
A009/210 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40768126	[ ]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016085	
38.316004000000		\\ - \( \)
-121.9396160000	1. Yolz Ha	as "C" Trans
A009/211 SINGLE WOOD POLE		Total # of Attachments:
40767475	[]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016086	
38.315671000000		
-121.9399820000		
A009/212 SINGLE WOOD POLE		Total # of Attachments:
40825127	[ ]completed/new finding(s)	,
TRI POST .	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016087	
38.315111000000		
-121.9404290000		
A009/213 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
10816655	[ ]completed/new finding(s)	0
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016088	
8.31464900000		
121_9408150000		
009/214 SINGLE WOOD POLE		Total # of Attachments:
0875427	[ ]completed/new finding(s)	
RI POST	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: C016089	
8.314243000000	and the second second	
121.9411090000		
010,215 SINGLE WOOD POLE		Total # of Attachments:
0868374	[]completed/new finding(s)	
RI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016090	
8.313557000000		"c" Truss
121.9416300 <b>00</b>		

Page 70

Funct Loc : ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Date Inspected: 3-23-12

Inspector Name : COOPER

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A010/216 SINGLE WOOD POLE	Teempleted/no problems	Total # of Attachments:
40612549	[ ]completed/new finding(s)	
TRI POST .	[ ]pre-existing cond chked	.0 .0
	[]not inspetd this patrol	our True
	Notes: '02 Survey: C016091	7.0.00
38.313088000000		
-121.9419650000		
A010/217 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40592648	[ ]completed/new finding(s)	
TRI POST	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
19 217577000000	Notes: '02 Survey: C016092	
38.312570000000 -121.9423280000		
A010/218 SINGLE WOOD POLE 40677842	completed/no problems	Total # of Attachments:
40677842 Tri Post	[ ]completed/new finding(s)	
IRI POST	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
38.311951000000	Notes: '02 Survey: C016093	
-121.9427380000 A010/219 SINGLE WOOD POLE		
40599382	completed/no problems	Total # of Attachments:
IRI POST	[ ]completed/new finding(s)	
281 7031	[]pre-existing cond chked	
	[]not inspetd this patrol	
38.31140900000	Notes: '02 Survey: C016094	
-121.9430450000		
1010/220 SINGLE WOOD POLE		
0677846	[ ]completed/new finding(s)	Total # of Attachments:
TRI POST	[ ]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C016095	
8.310789000000	Modes: 402 Survey: Co16095	
121.9434210000		
010/221 SINGLE WOOD POLE	]completed/no problems	Potal # of Attack
0657560	[]completed/new finding(s)	Total # of Attachments:
RI FOST T-1(c)	[]pre-existing cond chked	
1-1(6)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016096	
8.310137000000	27 201 vey : C010038	
121.9438270000		
010/222 SINGLE WOOD POLE		Total # of Attachments:
0768111	[]completed/new finding(s)	TOTAL WOLL ACCOUNTERING:
NGLE 0-30 DEGREES	[] pre-existing cond chked	
51	[]not inspctd this patrol	
	Notes: '02 Survey: C016097	
8.309471000000		
121.9439840000	har a second	
010/223 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0767496	[ ]completed/new finding(s)	
VERTICAL SHORT POST	[ ]pre-existing cond chked	
1949HE	[ ]not inspctd this patrol	
	Notes: '02 Survey: C016098	
3.308824000000		
.21.9443680000		

Page 71

Inspector Name : COOPER

Date Inspected : 3-23-12

Funct Loc: ETL.6740.POLE.WOOD 60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		- IPO, UNECT HIBSEN
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		•
A010/224 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40825125	[ ]completed/new finding(s)	Total W of McCachinettes:
TRI POST (C)	[ ]pre-existing cond chked	
1/~ 1/ ,	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016099	
38.308308000 <b>00</b>		· · · · · · · · · · · · · · · · · · ·
-121.9446900000		
A010/225 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40816657	completed/new finding(s)	TOTAL # OF ACCACHMENTS:
TOST (C)	[ ]pre-existing cond chked	1
-(-)(0)	[ ]not inspetd this patrol	*(2) 1
	Notes: '02 Survey: C016100	MY AUTO SPLICES AT HOLE.
38.307575000000	2 om 2 co19100	Middle Phase
-121.9451490000		1 ALL ANDER
A010/226 SINGLE WOOD POLE	completed/no problems	
0875425	[ ]completed/new finding(s)	Total # of Attachments:
TEOST	[ ]pre-existing cond chked	
1-1(c)		
1-4-3	[] not inspetd this patrol	
8.307023000000	Notes: '02 Survey: C016101	
121.9454700000		
010/227 SINGLE WOOD POLE		
0868375	/completed/no problems	Total # of Attachments:
RI POST	[ ]completed/new finding(s)	
T-(c)	[ ]pre-existing cond chked	
(~y~)	[ ]not inspetd this patrol	
0. 30634 800000	Notes: '02 Survey: C016102	
8.306315000000		
121.9458830000		
010/228 SINGLE WOOD POLE 0612574	Completed/no problems	Total # of Attachments:
7612574 21 Dogs	[ ]completed/new finding(s)	
7-1(c)	[ ]pre-existing cond chked	
(-/(0)	[ ]not inspetd this patrol	
	Notes: '02 Survey: C016103	
3.305737000000		
21.9462360000		
10/229 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
592649	[ ]completed/new finding(s)	And the second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second s
T FOST T- ((C)	[ ]pre-existing cond chked	
•	[ ]not inspctd this patrol	
	Notes: '02 Survey: C016104	
.305053000000		
21.9465820000		
10/230 SINGLE WOOD POLE	completed/no problems T	Potal # of Attachments:
595414	[ ]completed/new finding(s)	" a vicinities:
LDOST (C)	[ ]pre-existing cond chked	
T-(c)	[ ]not inspctd this patrol	
	Notes: '02 Survey: C016105	
304445000000		
1.9468820000		
0/231 SINGLE WOOD POLE	completed/no problems T	otal # of Athana
57561	[ ] completed/new finding(s)	otal # of Attachments:
POST - \(CC\)	[ ]pre-existing cond chked	
POST (C)	[ ] not inspetd this patrol	
	Notes: 102 current patrol	
303766000000	Notes: '02 Survey: C016106	
21.9473620000		

Page 72

Inspector Name : ____ Date Inspected : _

Funct Loc : ETL.6740.POLE.WOOD

60067 DIXON-VACA #2+-WOOD POLE

Order : 41620567 PATR/INSP 60067 DIXON-VACA #2+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip # Framing Config Access:		Attachment Type/Owner Listed
HOST Tech ID/Equip #: Lat: Long:	Notes	
A010/232 SINGLE WOOD POLE 40768113	[]completed/no problems []completed/new finding(s) []pre-existing cond chked	Total # of Attachments:
7-1(6)	[ ]not inspctd this patrol Notes: '02 Survey: C016107	
38.303171000000 -121.9477190000		
A010/233 SINGLE WOOD POLE SW 27 A0759696 FIELD SWITCH STRUCTURE MEDIUM EQP(AERIAL LIFT; LINE TR	[]completed/new finding(s) []pre-existing cond chked []not inspetd this patrol	Total # of Attachments:
8.302519000000 121.9481360000	Notes:	
007/179 SINGLE WOOD POLE 1122279 LAT PIN ARM	[]completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspetd this patrol Notes: '02 Survey: C015771	Total # of Attachments:
8.445045000000 121.8259260000	12 12 13 10 10 10 10 10 10 10 10 10 10 10 10 10	

0.0m2 D.0m4

E	ì				N N		(A)(A)	<u>}</u>						(	9	3		>		1	n r	h.	(	N.			×	,	<del>Le</del>	P	lu-	ı	
111700432	CCH/00111	111077400	111737650	111737836	111739210	111624771	111476838	11.1624744	111810715	111446988	111418017	110544132	110544135	111571213	111521524	108864064	106888338	111129655	110472422	111822202	111821903	110480769	111474335	111624635	109964649	104432640	111742077	111305855	111748938	11748937	11749507	Notification	
5 5	1	5 6	2	ก	רכ	Г	ក	ก	ন	ñ	5	ন	FC.	ī.	ГО	5	CO	LC	۲ ا	Ю	LC	5	LC .	5	ন	10	5	ıc	IC.	100	LC	type	Notification
m r		ñ		m	m	68	m	0		m	m		m	m	m	m	A		m	П				m	-		<u>u</u>					Priority	
E - Scho Compl Yr 0	E - Schol Compl Yr 0	E - Schd Compl Yr O	E - Schd Compl Yr 0	E - Schd Compl Yr 0	E - Schd Compl Yr 0	B - Urgt Compliance	E - Schd Compland	B - Orgi Compilarice	E - Send Compilar o	E - Schd Compl Yr 0	E - Schd Compl Yr U	E - Schd Compl Yr 0	E - Schd Compl Yr 0	E - Schd Compl Yr 0	E - Schd Compl Yr O	E - Schd Compl Yr 0	A - Immed/Sarety	E - Schd Complitin	E - Schd Compi Yr U	1 1	E - Schd Compl Yr U	- Scho Compliated	5chd Compl Yr 1+	E - Schd Compl Yr O	E - Schd Compliff O	E - Schd Compl Yr O	B - Orgi Compilance	k - Schd Compl Yr U	E - Selid Compiler of	E - Send Compiler	E - Schd Conipl Tr V	Priority Description	Daniel I
WEBER-TESLA 37/248 FOUNDATION CRACKED	WEBER-TESIA 35/237 REMOVE FENCE	WEBER-TESLA 31/208 REMOVE BIRO NEST	WEBER-TESIA 25/169 REMOVE TREES	WEBER-TESTA 19/131 AND CHAIRING	WEBER-IESIA 14/101 KENIOVE DEGREE	WEBER-IESUA COMOCIONIESIS	TESTA TOTAL SOLVENING DELICATION OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPER	TEST A TRACK 32/220 BENT STEEL LEG	TESTA TRACY 32/210 MEASUREO HEIGHT	TESTA TRACE 31/203 BORREO COLORO	TESTA-TRACT 23/133 STEEL	TESTA TRACT 21/141 VCG	TESTA-TRACY 20/136 VEG	IESLA-IRACY 18/125 MIDAN BACCOM	TESTA-TRACT ZUID IN FAIRNOUT SIX	TESTA IRACT 007/039 BIND OIN CECTS	LOCKEFORO INCOSTRIBLIOSO/ COT INC. CO.	LOCKETORO INICIISTRIAI 000/004 REPIC POLE	LOCKEFORO INOUSINAL WAS SIGN	LOCKETONO #1 0/100 CWC.com	LOCKETORD #1 9/150 ANCHOR	LOCKEFORD #1 A/64 HV	LOCKETORO #1 0/1 GROUND MOLDING	KYOHO TAP 0/4 ACCESS ISSUES	KASSON-CARBONA OF TRAIN THE	CAMANCHE IAP 00/000 REMOVE TO TO THE	DELLO INTEGER TO COME DEMONE ALLTO SPINCE F	BELLOTA WEBER TOWER 12/86 NR GRD PATROL	DELLOTA WEBER 17/86 - BENT STEEL MEMBER	DELICITA WERER 6/43 CHMB GUARO	BELLOTA WERER A/32 HV	TOTA WEEDED 13/00 VEG	Description
VICTOR	VICTOR	VICTOR	ALCION	AICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	VICTOR	Main WorkCtr
5/26/2016	5/26/2016	07/20/2016	0707770	2,007,0016	06/07/2016	06/22/2016	05/05/2016	03/25/2016	05/05/2016	7/20/2016	03/15/2016	03/03/2016	07/29/2015	07/29/2015	04/24/2016	04/07/2016	08/08/2014	04/24/2013	12/23/2015	06/24/2015	7/19/2016	07/11/2016	06/23/2015	3/23/2016	5/5/2016	01/13/2015	01/07/2010	06/23/2016	01/13/2016	6/23/2016	06/23/2016	6/23/2016	Oate
5/26/2017	5/26/201/	/10//01/	1202/2027	6/2/2017	06/07/2017	06/22/2017	08/03/2016	03/25/2017	08/03/2016	7/20/2017	03/15/2017	03/03/2017	07/29/2016	07/29/2016	07/23/2016	04/07/2017	08/08/2015	04/30/2013	12/23/2016	06/24/2016	7/19/2017	07/11/2017	06/23/2016	3/23/2018	5/5/2017	01/13/2016	07/31/2014	09/21/2016	01/13/2017	6/23/2017	06/23/2017	6/23/2017	Due Date
		01/20/2010 42/44550	2100,000		06/23/2016 31249143 Closed	06/23/2016 42730102 Closed	05/05/2016 4269B738 Closed	04/20/2016 42670320 Closed	05/05/2016 42698736 Closed		05/09/2016 42 <b>692500</b> Closed	05/16/2016 42648B12 Closed	05/23/2016	06/24/2016	0S/03/2016 42684B23 Closed	06/17/2016 42639345 Closed	07/13/2015 42170137 Closed	05/31/2016 30992927 Closed	02/04/2016 42S98224 Closed	07/15/2015 42417490 Closed		09/12/2016 42753S95   Closed	09/22/2015 42417720 Closed			01/13/2015 42319492 Closed	06/29/2015 42409953 Closed	06/28/2016 42731000 Closed	02/18/2016 42623130 Closed		07/28/2016 42733443 Closed		Completion Date
		1200000	95077777		31249143	42730102	42698738	42670320	42698736	31259661 Open	42692500	42648B12			42684823	42639345	42170137	30992927	42598224	42417490	427535B6 Open	42753595	42417720	31227563 Open	42724477 Open	42319492	42409953	42731000	42623130	31250356 Open	42733443		Order
Open	open			Open	Closed	Closed	Closed	Closed	Closed	Open	Closed	Closed	Closed	Closed	Closed	Closed	Closed	Closed	Closed	Closed	Open	Closed	Closed	Open	Open	Closed	Closed	Closed	Closed	Open	Closed	Open	Open/Closed
NO	2	3	2	N _o	No	No	20	No	8	S	No	8	S	No	No	No	8	Yes	No	S	No	8	8	S	No	8	Yes	No	NO	No	8	NO	